



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE TDI 105BHP
Colour	Red
Year of manufacture	2010
Top speed	111 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	240 Nm at 1.800 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	58.9 mpg
Consumption combined	50.4 mpg
CO2 emission	143 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-07-20
Pictures	7
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-01
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	25
Total items failed	9

MOT #15	2023-08-01 16:38
MOT test number	605346564094
Result	✓ Passed
Next expiry date	2024-08-01
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #14	2022-07-12 11:45
MOT test number	904481135393
Result	✓ Passed

MOT #13	2021-08-02 08:37
MOT test number	560598584602
Result	✓ Passed

**MOT #12**

2020-07-09 08:19

MOT test number

801294741260

Result

✓ Passed

Minor

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #11

2020-07-09 08:19

MOT test number

862159973260

Result

✗ Failed

Pass with rectification

Nearside Front Headlamp not working on main beam (4.1.1 (a) (ii))

Minor

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Pass with rectification

Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice

Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #10

2019-06-14 11:38

MOT test number

171490272461

Result

✓ Passed

Advice

Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice

Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #9** 2019-06-14 08:31**MOT test number** 877590497918**Result** ✗ Failed**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #8** 2018-06-19 10:47**MOT test number** 965453090841**Result** ✓ Passed**Advice** Rear exhaust box corroded**MOT #7** 2018-06-19 08:54**MOT test number** 465111844833**Result** ✗ Failed**Advice** Rear exhaust box corroded**Fail** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #6** 2017-06-26 11:46**MOT test number** 347242133027**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)

MOT #5 2017-06-26 09:14**MOT test number** 580702114082**Result** ✗ Failed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #4 2016-06-29 14:15**MOT test number** 156666829339**Result** ✓ Passed**MOT #3** 2015-06-30 18:08**MOT test number** 455581885184**Result** ✓ Passed



MOT #2	2014-06-17 14:38
MOT test number	938108364189
Result	✓ Passed

MOT #1	2013-06-18 11:22
MOT test number	518729263115
Result	✓ Passed

Notice Child seat fitted not allowing full inspection of adult belt



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
1 August 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	1 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2023-03-29
Current registration	 XXXXXX
Plate since	2023-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-05-27
Last registration	2023-08-01
Complete history	See info



Registration #1	2010-05-27	6 mi
Registration #2	2013-06-18	27.908 mi
Registration #3	2014-06-17	35.592 mi
Registration #4	2015-06-30	44.301 mi
Registration #5	2016-06-29	50.909 mi
Registration #6	2017-06-26	60.016 mi
Registration #7	2017-06-26	60.016 mi
Registration #8	2018-06-19	68.036 mi
Registration #9	2018-06-19	68.036 mi
Registration #10	2019-06-19	68.036 mi
Registration #11	2019-06-19	68.036 mi
Registration #12	2019-06-19	68.036 mi
Registration #13	2019-06-19	68.036 mi
Registration #14	2019-06-19	68.036 mi
Registration #15	2019-06-19	68.036 mi
Registration #16	2019-06-19	68.036 mi
Registration #17	2019-06-19	68.036 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2516 mm
Kerb weight	1370 kg
Max. allowed weight	1720 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BSW 020740