




report date: 2024-03-29

General information

Make	BMW
Model	M3
Colour	White
Year of manufacture	2012
Top speed	155 mph
Gearbox	7 speed Semi-Automatic

Engine & fuel consumption

Power	414 BHP
Max. torque	400 Nm at 3.900 rpm
Engine capacity	3.999 cc
Cylinders	8
Fuel type	Petrol
Consumption city	17.8 mpg
Consumption extra urban	33.2 mpg
Consumption combined	25.2 mpg
CO2 emission	263 g/km
CO2 label	M





Internet history

Entry 5

Date	2023-08-03
Pictures	0
Listing price	View report

source: carcraft.co.uk

Entry 4

Date	2023-04-26
Pictures	0
Listing price	View report

source: carcraft.co.uk

Entry 3

Date	2023-02-13
Pictures	0
Listing price	View report

source: carcraft.co.uk

Entry 2




Date	2021-12-22
Pictures	1
Listing price	View report



source: autotrader.co.uk

Entry 1

Date	2021-10-14
Pictures	9
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-09
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	26
Total items failed	4

MOT #11	2023-08-10 10:04
MOT test number	705553724453
Result	✓ Passed
Next expiry date	2024-08-09

MOT #10	2022-03-28 14:51
MOT test number	950851272108
Result	✓ Passed

MOT #9	2022-03-21 17:11
MOT test number	451836298448
Result	✗ Failed
Fail	Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
Fail	Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
Fail	Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
Fail	Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

**MOT #8**

2021-11-24 10:11

MOT test number

338891153137

Result

✓ Passed

- Advice** Central Rear Exhaust has a minor leak of exhaust gases o/s pipe has hairline crack next to clamp (6.1.2 (a))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material pipe between flexi's swelling/corrosion under coating (1.1.11 (c))
- Advice** Nearside Rear Parking (secondary brake) grabbing slightly (1.3.1 (c))
- Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Central Rear heat shield loose
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Central Rear Brake pipe corroded, covered in grease or other material both central pipes into flexi swelling/corrosion under coating (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material pipe between flexi's swelling/corrosion under coating (1.1.11 (c))
- Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Rear Parking (secondary brake) grabbing slightly (1.3.1 (c))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #7

2020-12-10 13:51

MOT test number

372111087495

Result

✓ Passed

- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Parking (secondary brake) grabbing slightly (1.3.1 (c))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Parking (secondary brake) grabbing slightly (1.3.1 (c))

**MOT #6** 2019-12-12 09:53**MOT test number** 953028538098**Result** ✓ Passed**Advice** Nearside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement Inner (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2018-12-12 14:31**MOT test number** 462848221164**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #4** 2018-06-20 13:53**MOT test number** 329229432147**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #3** 2017-10-24 12:26**MOT test number** 798497070920**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2016-09-30 13:47**MOT test number** 138846942559**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



MOT #1	2015-10-27 16:32
MOT test number	912175757116
Result	✓ Passed
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Front Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)
Advice	Oil leak



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
9 August 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	9 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	RE62GZG
Plate since	2024-03-29
Current registration	RE62GZG
Plate since	2024-03-29

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-10-30
Last registration	2023-08-10
Complete history	See info



Registration #1	2012-10-30	9 mi
Registration #2	2015-10-27	28.901 mi
Registration #3	2016-09-30	34.640 mi
Registration #4	2017-10-24	41.848 mi
Registration #5	2018-06-20	44.767 mi
Registration #6	2018-12-12	45.844 mi
Registration #7	2019-12-12	55.644 mi
Registration #8	2020-12-10	60.257 mi
Registration #9	2020-12-10	60.257 mi
Registration #10	2020-12-10	60.257 mi
Registration #11	2020-12-10	60.257 mi
Registration #12	2020-12-10	60.257 mi
Registration #13	2020-12-10	60.257 mi
Registration #14	2020-12-10	60.257 mi
Registration #15	2020-12-10	60.257 mi
Registration #16	2020-12-10	60.257 mi
Registration #17	2020-12-10	60.257 mi

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	78%
Safety systems	86%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	1804 mm
Height	1424 mm
Length	4615 mm
Wheel base	2761 mm
Kerb weight	1600 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	63 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	22740320