





report date: 2024-03-29

General information

Make	VAUXHALL
Model	MOVANO L2H1 F3500 TIPPER
Colour	White
Year of manufacture	2018
Top speed	91 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	129 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	2.299 сс
Cylinders	4
Fuel type	Diesel
Consumption city	31.4 mpg
Consumption extra urban	39.2 mpg
Consumption combined	35.8 mpg
CO2 emission	207 g/km
CO2 label	K



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date	2021-08-10
Pictures	1
Listing price	View report



source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT expiry date	2025-03-29
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	22
Total items failed	5

MOT #6	2024-03-14 10:19
MOT test number	329193685613
Result	✓ Passed
Next expiry date	2025-03-29

MOT #5		2023-03-07 13:08
MOT test	number	789747367288
Result		✓ Passed
Advice	Brake pedal wearing smooth (1.1.2 (c))	
Advice	Offside Rear Shock absorbers has slight external damage to the casing corro	oded (5.3.2 (b))
Advice	Offside Front Shock absorbers has slight external damage to the casing corre	oded (5.3.2 (b))
Advice	Offside Rear leaf spring corroded	
Advice	Nearside Rear Shock absorbers has slight external damage to the casing cor	rroded (5.3.2 (b))
Advice	Nearside Front Shock absorbers has slight external damage to the casing co	rroded (5.3.2 (b))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Rear leaf spring corroded	

MOT #4	2022-03-17 17:19
MOT test number	183255808459
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #3 2022-03-16 14:56

MOT test number 247026132340

Result X Failed

Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Nearside All outline marker lamps with a multiple light source more than 1/2 not functioning (4.2.1 (a) (ii))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Fail Offside All outline marker lamps missing 1 missing (4.2.1 (a) (ii))

MOT #2 2021-03-23 10:53

MOT test number 316494512825

Advice Spare tyre defective

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Rear lamp unit cracked

Advice Nearside Front Nail in tyre

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Central Upper brake light unit taped into door

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #1 2021-03-22 09:09 197848652259 **MOT test number** Result × Failed **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Nearside Rear lamp unit cracked Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b)) Advice Nearside Front Nail in tyre Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Central Upper brake light unit taped into door Spare tyre defective **Advice**

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	29 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29


Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	
Туре	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner history	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloaner.	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	IK NEW TOTAL
Plate since	
Current registration	OK OK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-03-30
Last registration	2024-03-14
Complete history	See info



Registration #1	2018-03-30	10 mi
Registration #2	2021-03-22	93.408 mi
Registration #3	2021-03-23	93.409 mi
Registration #4		11.777 es
Registration #5		9.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Adult	96%
Children	90%
Pedestrian	67%
Safety systems	100%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	2470 mm
Height	2370 mm
Length	5819 mm
Kerb weight	2306 kg
Max. allowed weight	3500 kg

Additional information

Number of seats	3
Number of axles	2
Engine number	M9T -C132152 L0B

CarCheck.co.uk page 12/12