





General information

Make	FIAT
Model	SEDICI 16V DYNAMIC
Colour	Grey
Year of manufacture	-
Top speed	106 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	106 BHP
Max. torque	145 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	46.3 mpg
Consumption combined	39.8 mpg





Internet history

Entry	1
Date	

Pictures

2021-09-04

11

Listing price

View report



source: autotrader.co.uk



MOT history

MOT #16	2021-09-06 16:42
MOT test number	427395733407
Result	✓ Passed
Next expiry date	2022-09-28
Minor Headlamp lens slightly defective nearside and offside front (4.1.1 (b) (i))	
Advice Nearside and offside rear	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Handbrake travel slightly high	

MOT #15	2020-09-29 15:21
MOT test	number 808252926758
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice (ii))	Offside Front Tyre slightly damaged/cracking or perishing also wearing low on 2.5mm (5.2.3 (d)
Advice	Oil leak, but not excessive gearbox area (8.4.1 (a) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #14	2020-09-15 13:29
MOT test number	882544771079
Result	🗙 Failed
Advice Offside Front Tyre slightly damaged/cracking or perishing also wearing low (ii))	w on 2.5mm (5.2.3 (d)
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice Oil leak, but not excessive gearbox area (8.4.1 (a) (i))	





MOT #13	2019-08-16 12:55
MOT test number	621080100677
Result	✓ Passed
AdviceNearside Rear Inner Child Seat fitted not allowing full inspection of adult beltAdviceFront various corrosions underbodyAdviceRear various corrosions underbody	
MOT #12	2019-08-16 06:22
MOT test number	230879974302
Result	🗙 Failed

hesuit	
Fail Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))	
Advice Front various corrosions underbody	
Fail Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))	
Advice Nearside Rear Inner Child Seat fitted not allowing full inspection of adult belt	
Fail Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))	
Advice Rear various corrosions underbody	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail Central Rear Brake lever has insufficient reserve travel BOTH (1.1.2 (a))	

MOT #11	2018-07-27 14:01
MOT test number	666695237334
Result	✓ Passed





MOT #10		2017-08-19 13:14
MOT test i	number	671071369574
Result		Passed
Advice Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Oil leak	
MOT #9		2017-08-19 10.07

	2017-08-19 10:07
MOT test number	483567760653
Result	🗙 Failed
Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Fail Offside Front coil spring broken (2.4.C.1a)	
Advice Oil leak	

MOT #8	2016-08-03 09:59
MOT test number	246538950967
Result	✓ Passed

MOT #7	2015-08-08 11:55
MOT test number	788200525205
Result	✓ Passed

МОТ #6	2014-08-18 09:22
MOT test number	375110834417
Result	✓ Passed

MOT #5	2013-08-07 09:32
MOT test number	285789613223
Result	✓ Passed





MOT #4		2012-04-20 10:03
MOT test number		605841912101
Result		✓ Passed
МОТ #3		2012-04-20 10:03
MOT test number		236641812429
Result		🗙 Failed
Pass with rectification	Offside Front Windscreen wiper blade insecure (8.2.2)	
Pass with rectification	Nearside Front Windscreen wiper blade insecure (8.2.2)	

MOT #2	2011-05-12 11:02
MOT test number	845992331116
Result	✓ Passed

MOT #1		2010-05-14 10:20
MOT test	number	372204830159
Result		✓ Passed
Notice	Rear wiper blade split	
Notice	Unable to fully inspect outer sills due to covers being fitted	
Notice	Slight wear in n/s steering rack arm	
Notice	Brakes require stripping down and inspecting	





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Duniuge 2	E E E E
Date	J.
Category	amer
Туре	

Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-05-19
Last registration	2021-09-06
Complete history	See info



Registration #1 2007-05-19 1 Registration #2 2010-05-14 16.77 Registration #3 2011-05-12 28.00 Registration #4 2012-04-20 31.61 Registration #5 2013-08-07 35.23 Registration #6 2014-08-18 40.16 Registration #7 2015-08-08 42.09 Registration #8 2016-08-03 44.56	01 mi L4 mi 34 mi
Registration #3 2011-05-12 28.00 Registration #4 2012-04-20 31.61 Registration #5 2013-08-07 35.23 Registration #6 2014-08-18 40.16 Registration #7 2015-08-08 42.09	01 mi L4 mi 34 mi
Registration #4 2012-04-20 31.61 Registration #5 2013-08-07 35.23 Registration #6 2014-08-18 40.16 Registration #7 2015-08-08 42.09	L4 mi 34 mi
Registration #5 2013-08-07 35.23 Registration #6 2014-08-18 40.16 Registration #7 2015-08-08 42.09	34 mi
Registration #6 2014-08-18 40.16 Registration #7 2015-08-08 42.09	
Registration #7 2015-08-08 42.09	
-	54 mi
Registration #8 2016-08-03 44.56	96 mi
	53 mi
Registration #9 2017-08-19 46.95	56 mi
Registration #10	7.06
Registration #11	7 44
Registration #12	7.06
Registration #13	7 44
	17 mi
Registration #14	
Registration #14 Registration #15	7 mi
	17 mii 17 mii





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1755 mm
Height	1620 mm
Length	4115 mm
Wheel base	2500 mm
Kerb weight	1195 kg
Max. allowed weight	2870 kg
Additional information	
Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles	2
Engine number	8003285