



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D DRIVE SE LUX
Colour	Grey
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-07-27
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2023-08-30
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	11
Total items failed	2

MOT #10	2022-08-26 11:54
MOT test number	494942598796
Result	✓ Passed
Next expiry date	2023-08-30
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened x 2 (1.1.14 (a) (ii))
Advice	Wipers smearing screen

MOT #9	2021-08-31 12:39
MOT test number	170662750312
Result	✓ Passed
Advice	Registration plate deteriorated but not likely to be misread Both (0.1 (b))
Advice	Rear Tyre slightly damaged/cracking or perishing both tyres feathered on inner edges (5.2.3 (d) (ii))

MOT #8	2021-01-28 10:01
MOT test number	831107161301
Result	✓ Passed
Advice	Rear exhaust hangers corroded
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #7** 2020-01-22 14:21**MOT test number** 205560256849**Result** ✓ Passed**MOT #6** 2019-02-11 15:32**MOT test number** 231893810951**Result** ✓ Passed**MOT #5** 2019-02-11 12:39**MOT test number** 486954271631**Result** ✗ Failed**Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #4** 2017-03-27 13:51**MOT test number** 917619693236**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit Stepped and mishaped (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Oil leak Gearbox area**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**MOT #3** 2016-03-15 09:17**MOT test number** 391504864411**Result** ✓ Passed



MOT #2	2015-03-09 16:24
MOT test number	888558265087
Result	✓ Passed

MOT #1	2014-03-08 09:22
MOT test number	986297464001
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
10 October 2022

✕
MOT

Expired:
30 August 2023

Tax status	Expired at 10 October 2022
Days left	568 days too late
MOT expiry date	30 August 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2011-03-30
Last registration	2022-08-26
Complete history	See info



Registration #1	2011-03-30	8 mi
Registration #2	2014-03-08	38.401 mi
Registration #3	2015-03-09	54.588 mi
Registration #4	2016-03-15	69.123 mi
Registration #5	2017-03-27	80.452 mi
Registration #6	2019-02-11	102.536 mi
Registration #7	2020-08-26	121.277 mi
Registration #8	2021-08-26	131.277 mi
Registration #9	2022-08-26	141.277 mi
Registration #10	2023-08-26	151.277 mi
Registration #11	2024-03-29	161.277 mi
Registration #12	2024-03-29	171.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1760212