



report date: 2024-03-28

General information

Make	VAUXHALL
Model	TIGRA SPORT
Colour	Black
Year of manufacture	2011
Top speed	112 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	125 Nm at 4.000 rpm
Engine capacity	1.364 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.3 mpg
CO2 emission	146 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-02-05
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-08-18
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	32
Total items failed	2

MOT #13	2023-08-11 10:29
MOT test number	780062600106
Result	✓ Passed
Next expiry date	2024-08-18
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Minor	Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Front Suspension component corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**MOT #12** 2023-08-11 10:29**MOT test number** 371883706898**Result** ✗ Failed

- Advice** Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Front Suspension component corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Pass with rectification** Rear Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #11 2022-08-19 15:14**MOT test number** 295330112206**Result** ✓ Passed**MOT #10** 2022-08-18 09:36**MOT test number** 612728388751**Result** ✗ Failed

- MAJOR** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- MAJOR** Nearside Brake pipe excessively corroded FRONT TO REAR (1.1.11 (c))
- DANGEROUS** Stop lamp(s) all not working (4.3.1 (a) (iii))

MOT #9 2021-03-04 10:31**MOT test number** 231379855393**Result** ✓ Passed

**MOT #8** 2019-04-16 16:04**MOT test number** 720487305884**Result** ✓ Passed**Advice** Central Exhaust has a minor leak of exhaust gases box (6.1.2 (a))**Advice** Oil pressure light has intermittent fault**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))**MOT #7** 2019-04-16 10:46**MOT test number** 715156513013**Result** ✗ Failed**Advice** Oil pressure light has intermittent fault**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))**Advice** Central Exhaust has a minor leak of exhaust gases box (6.1.2 (a))**MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 205/50/16 (5.2.3 (d) (i))**MAJOR** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**MAJOR** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #6** 2018-04-23 08:56**MOT test number** 186636570091**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2017-04-05 14:36**MOT test number** 172844046266**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit worn on inner edge (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit worn on inner edge (4.1.E.1)**MOT #4** 2017-04-05 08:32**MOT test number** 878976590658**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm cracked down to chords (4.1.E.1)**Advice** Oil leak engine**Advice** Offside Front Tyre worn close to the legal limit worn on inner edge (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit worn on inner edge (4.1.E.1)**MOT #3** 2016-04-18 07:48**MOT test number** 347860248811**Result** ✓ Passed**MOT #2** 2015-04-24 12:50**MOT test number** 769544415139**Result** ✓ Passed**MOT #1** 2014-04-11 09:24**MOT test number** 136011104104**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
18 August 2024

Tax status	Valid until 1 March
Days left	306
MOT expiry date	18 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-04-21
Last registration	2023-08-11
Complete history	See info



Registration #1	2011-04-21	20 mi
Registration #2	2014-04-11	28.166 mi
Registration #3	2015-04-24	31.367 mi
Registration #4	2016-04-18	34.893 mi
Registration #5	2017-04-05	37.416 mi
Registration #6	2017-04-05	37.420 mi
Registration #7	2018-04-23	46.477 mi
Registration #8	2019-04-16	59.510 mi
Registration #9	2020-04-05	72.547 mi
Registration #10	2021-04-05	85.584 mi
Registration #11	2022-04-05	98.621 mi
Registration #12	2023-04-05	111.658 mi
Registration #13	2024-04-05	124.695 mi
Registration #14	2025-04-05	137.732 mi
Registration #15	2026-04-05	150.769 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2033 mm
Height	1415 mm
Length	4290 mm
Wheel base	2614 mm
Kerb weight	1168 kg
Max. allowed weight	1715 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Engine number	19UF4006