



Mercedes-Benz

K352LLG

report date: 2024-03-28

General information

Make	MERCEDES
Model	SL
Colour	Red
Year of manufacture	1993
Top speed	142 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	190 BHP
Max. torque	134 Nm at 4.500 rpm
Engine capacity	2.960 cc
Cylinders	6
Fuel type	Petrol



LABEL UNKNOWN



Internet history

Entry 2


Date	2021-09-11
Pictures	11
Listing price	View report



source: autotrader.co.uk

Entry 1

Date	2021-06-19
Pictures	11
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-06-17
MOT pass rate	74 %
MOT passed	17
Failed MOT tests	6
Total advice items	42
Total items failed	9

MOT #23	2022-06-13 15:47
MOT test number	839632554319
Result	✓ Passed
Next expiry date	2023-06-17

MOT #22	2021-06-18 13:42
MOT test number	720500259141
Result	✓ Passed

MOT #21	2021-06-17 08:30
MOT test number	711271812457
Result	✗ Failed
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Nearside Front Brake pipe excessively corroded (1.1.11 (c))

MOT #20	2020-06-05 11:00
MOT test number	743441669765
Result	✓ Passed



MOT #19	2019-05-31 13:55
MOT test number	342468572315
Result	✓ Passed
Advice	Brake pipe corroded, covered in grease or other material main front to rear brake pipes (1.1.11 (c))

MOT #18	2018-05-31 11:23
MOT test number	173809097460
Result	✓ Passed

MOT #17	2017-05-31 13:56
MOT test number	335472289890
Result	✓ Passed
Advice	Nearside Front Front wheel bearing has slight play (2.5.A.3c)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Brake pipe slightly corroded front to rear (3.6.B.2c)
Advice	Engine covers and undertrays fitted preventing a full inspection
Advice	Offside Front Front wheel bearing has slight play (2.5.A.3c)
Advice	Nearside Brake pipe slightly corroded front to rear (3.6.B.2c)
Advice	Oil leak

**MOT #16**

2017-05-30 12:00

MOT test number

591282073302

Result**✗ Failed****Advice** Nearside Front Front wheel bearing has slight play (2.5.A.3c)**Fail** Offside Front Brake pipe excessively corroded (3.6.B.2c)**Advice** Nearside Brake pipe slightly corroded front to rear (3.6.B.2c)**Advice** Oil leak**Advice** Offside Front Front wheel bearing has slight play (2.5.A.3c)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Engine covers and undertrays fitted preventing a full inspection**Advice** Offside Brake pipe slightly corroded front to rear (3.6.B.2c)**MOT #15**

2016-06-10 08:19

MOT test number

121149336374

Result**✓ Passed****Advice** Engine Covers and Undertray's fitted preventing a full inspection**Advice** Nearside Front Front wheel bearing has slight play (2.5.A.3c)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Front Front wheel bearing has slight play (2.5.A.3c)

**MOT #14** 2016-06-09 13:48**MOT test number** 971858934431**Result** ✗ Failed**Advice** Nearside Front Front wheel bearing has slight play (2.5.A.3c)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Engine Covers and Undertray's fitted preventing a full inspection**Advice** Offside Front Front wheel bearing has slight play (2.5.A.3c)**Fail** Driver's seat fore and aft adjustment mechanism not functioning as intended. (6.2.A.3)**MOT #13** 2014-07-09 12:41**MOT test number** 285110594465**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #12** 2013-10-04 15:37**MOT test number** 785777673250**Result** ✓ Passed**Notice** Oil leak**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**Notice** Brake pipes greased preventing full inspection

**MOT #11** 2013-10-04 08:55**MOT test number** 757447473291**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Notice** Brake pipes greased preventing full inspection**Notice** Oil leak**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Offside Rear Suspension component mounting prescribed area is excessively corroded (2.4.A.3)**MOT #10** 2012-10-03 14:48**MOT test number** 235877372268**Result** ✓ Passed**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #9** 2011-09-23 14:41**MOT test number** 706866161292**Result** ✓ Passed**MOT #8** 2010-09-28 16:59**MOT test number** 731031570267**Result** ✓ Passed**MOT #7** 2009-09-25 11:17**MOT test number** 422738569240**Result** ✓ Passed

**MOT #6** 2008-10-08 09:54**MOT test number** 993752988295**Result** ✓ Passed

- Advice** Offside Rear Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Offside Front wheel bearing has slight play (2.5.A.3c)
- Advice** Nearside Rear Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)
- Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)

MOT #5 2007-10-12 11:55**MOT test number** 664025087268**Result** ✓ Passed**MOT #4** 2007-10-11 08:17**MOT test number** 252274787291**Result** ✗ Failed

- Fail** Offside Rear Brake pipe excessively corroded (3.6.B.2c)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Fail** Nearside Rear Brake pipe excessively corroded (3.6.B.2c)
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Notice** Oil leak

MOT #3 2007-05-01 10:19**MOT test number** 321341027144**Result** ✓ Passed



MOT #2	2007-04-21 08:50
MOT test number	792021617133
Result	✗ Failed
Fail	Nearside Front coil spring cracked (2.4.C.1a)
Fail	Offside Front coil spring cracked (2.4.C.1a)

MOT #1	2006-03-29 16:42
MOT test number	833458986060
Result	✓ Passed



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 K352LLG
Plate since	2019-06-29
Current registration	 K352LLG
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	1993-02-12
Last registration	2022-06-13
Complete history	See info



Registration #1	1993-02-12	26 mi
Registration #2	2006-03-29	57.435 mi
Registration #3	2007-04-21	61.267 mi
Registration #4	2007-05-01	61.377 mi
Registration #5	2007-10-11	63.515 mi
Registration #6	2007-10-12	63.515 mi
Registration #7	2008-10-08	66.157 mi
Registration #8	2009-09-25	68.623 mi
Registration #9	2010-09-28	70.524 mi
Registration #10	2011-09-23	72.222 mi
Registration #11	2012-10-03	73.411 mi
Registration #12	2013-10-04	74.332 mi
Registration #13	2013-10-04	74.333 mi
Registration #14	2013-10-04	74.333 mi
Registration #15	2013-10-04	74.333 mi
Registration #16	2013-10-04	74.333 mi
Registration #17	2013-10-04	74.333 mi
Registration #18	2013-10-04	74.333 mi
Registration #19	2013-10-04	74.333 mi
Registration #20	2013-10-04	74.333 mi
Registration #21	2013-10-04	74.333 mi
Registration #22	2013-10-04	74.333 mi
Registration #23	2013-10-04	74.333 mi
Registration #24	2013-10-04	74.333 mi
Registration #25	2013-10-04	74.333 mi
Registration #26	2013-10-04	74.333 mi

More info >



Dimensions & weight

Width	1812 mm
Height	1286 mm
Length	4465 mm

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	2
Engine number	10398422008287