



report date: 2024-03-28

General information

Make	KIA
Model	SORENTO CRDI 1
Colour	Silver
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	194 BHP
Max. torque	422 Nm at 1.800 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	171 g/km
CO2 label	H





Internet history

Entry 2

Date	2021-06-25
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

Entry 1

Date	2021-06-23
Pictures	12
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-08
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	30
Total items failed	17

MOT #15	2023-07-06 06:35
---------	------------------

MOT test number	615862434535
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-07-08
------------------	------------

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #14**

2023-07-03 10:00

**MOT test number**

563444782601

**Result****✗ Failed**

- Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
- Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

**MOT #13**

2022-06-20 12:36

**MOT test number**

278389391903

**Result****✓ Passed**

- Advice** Brake disc worn, pitted or scored, but not seriously weakened both rears (1.1.14 (a) (ii))

**MOT #12**

2022-06-11 09:26

**MOT test number**

334413432027

**Result****✗ Failed**

**Fail** Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**Advice** Brake disc worn, pitted or scored, but not seriously weakened both rears (1.1.14 (a) (ii))

**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))

**Fail** Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))

**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))

**MOT #11**

2021-07-09 13:39

**MOT test number**

568489241692

**Result****✓ Passed**

**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #10**

2021-07-08 11:47

**MOT test number**

604484282938

**Result**

✗ Failed

- Fail** Offside Front Inner Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Offside Rear Anti-roll bar pin or bush excessively worn D bush (5.3.4 (a) (i))
- Fail** Nearside Front Inner Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Rear Brake pad(s) less than 1.5 mm thick rear pads (1.1.13 (a) (ii))
- Fail** Nearside Rear Anti-roll bar pin or bush excessively worn D bush (5.3.4 (a) (i))
- Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**MOT #9**

2020-10-06 13:27

**MOT test number**

765888087649

**Result**

✓ Passed

- Advice** Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #8**

2019-10-30 12:46

**MOT test number**

188456615099

**Result**

✓ Passed

**MOT #7**

2018-11-01 10:48

**MOT test number**

472085831220

**Result**

✓ Passed

**MOT #6** 2017-08-14 10:07**MOT test number** 207974790546**Result** ✓ Passed**MOT #5** 2017-01-12 09:40**MOT test number** 708231229240**Result** ✓ Passed**MOT #4** 2016-05-20 09:22**MOT test number** 894560030016**Result** ✓ Passed**Advice** Spare wheel missing**MOT #3** 2015-06-08 16:00**MOT test number** 235219655158**Result** ✓ Passed**Notice** Emission test aborted due to low readings.**MOT #2** 2014-04-16 13:32**MOT test number** 499666004169**Result** ✓ Passed**MOT #1** 2013-04-09 15:48**MOT test number** 796069393068**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Nearside rear tyre worn on inner edge.**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 July 2024

✓  
**MOT**  
  
Expires:  
8 July 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	8 July 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-04-18
Last registration	2023-07-06
Complete history	<a href="#">See info</a>



Registration #1	2010-04-18	27 mi
Registration #2	2013-04-09	24.727 mi
Registration #3	2014-04-16	33.729 mi
Registration #4	2015-06-08	36.780 mi
Registration #5	2016-05-20	52.583 mi
Registration #6	2017-01-12	57.484 mi
Registration #7	2017-08-14	61.673 mi
Registration #8	2018-11-01	71.723 mi
Registration #9	2019-10-30	78.639 mi
Registration #10	2020-05-20	85.555 mi
Registration #11	2021-05-20	92.471 mi
Registration #12	2022-05-20	99.387 mi
Registration #13	2023-05-20	106.303 mi
Registration #14	2024-05-20	113.219 mi
Registration #15	2025-05-20	120.135 mi
Registration #16	2026-05-20	127.051 mi
Registration #17	2027-05-20	133.967 mi
Registration #18	2028-05-20	140.883 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	84%
Pedestrian	44%
Safety systems	71%
Overall rating	76%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1885 mm
Height	1745 mm
Length	4685 mm
Wheel base	2700 mm
Kerb weight	1804 kg
Max. allowed weight	2510 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number

D4HB9U091134