



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	C C220 CDI SPORT
Colour	Grey
Year of manufacture	2009
Top speed	141 mph
0 - 60 mph	8.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	168 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.2 mpg
CO2 emission	177 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-02-02
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-07-13
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	39
Total items failed	12

MOT #18	2023-07-14 12:47
MOT test number	594669853252
Result	✓ Passed
Next expiry date	2024-07-13
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Nearside front tyre worn on edge and cracking
Advice	Rear subframe corroded

MOT #17	2023-07-13 12:44
MOT test number	128937408194
Result	✗ Failed
Fail	Offside Front Lower Suspension arm ball joint excessively worn rear arm (5.3.4 (a) (i))
Advice	Nearside front tyre worn on edge and cracking
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front Lower Suspension arm ball joint excessively worn rear arm (5.3.4 (a) (i))
Minor	Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Rear subframe corroded
Fail	Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #16** 2022-04-28 14:37**MOT test number** 722635964785**Result** ✓ Passed**MOT #15** 2022-04-28 07:59**MOT test number** 870246147368**Result** ✗ Failed**Advice** Nearside Front Outer Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #14** 2021-04-14 15:10**MOT test number** 149494898730**Result** ✓ Passed**MOT #13** 2020-09-24 10:28**MOT test number** 162243480374**Result** ✓ Passed**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii))

**MOT #12**

2020-09-18 11:18

MOT test number

607243578077

Result**✗ Failed**

- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #11

2019-09-23 09:53

MOT test number

642818516959

Result**✓ Passed**

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #10** 2019-09-16 16:06**MOT test number** 404120626414**Result** ✗ Failed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))**MOT #9** 2018-09-08 13:08**MOT test number** 460887577178**Result** ✓ Passed**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Rear Coil spring corroded both side (5.3.1 (b) (i))**MOT #8** 2017-09-09 12:08**MOT test number** 123977110140**Result** ✓ Passed**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Front Inner brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**Advice** Front Brake pipe slightly corroded bothside (3.6.B.2c)

**MOT #7** 2017-09-09 12:08**MOT test number** 848407858208**Result** ✗ Failed**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Front Brake pipe slightly corroded bothside (3.6.B.2c)**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Front Inner brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**MOT #6** 2016-09-03 08:39**MOT test number** 295249579929**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit 1.6mm (4.1.E.1)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2015-09-19 07:53**MOT test number** 346326881719**Result** ✓ Passed**Advice** Tyre worn close to the legal limit N/S/REAR (4.1.E.1)**MOT #4** 2014-09-16 14:18**MOT test number** 508739954235**Result** ✓ Passed**MOT #3** 2014-05-20 08:52**MOT test number** 278610144438**Result** ✓ Passed



MOT #2	2013-05-15 10:59
MOT test number	696805733146
Result	✓ Passed

MOT #1	2012-05-17 08:58
MOT test number	245308232416
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
13 July 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	13 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 KN09JXR
Plate since	2019-06-29
Current registration	 KN09JXR
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-05-20
Last registration	2023-07-14
Complete history	See info



Registration #1	2009-05-20	9 mi
Registration #2	2012-05-17	21.316 mi
Registration #3	2013-05-15	26.450 mi
Registration #4	2014-05-20	31.168 mi
Registration #5	2014-09-16	32.027 mi
Registration #6	2015-09-19	42.090 mi
Registration #7	2016-09-03	51.989 mi
Registration #8	2017-09-09	62.730 mi
Registration #9	2017-09-09	62.730 mi
Registration #10	2018-09-08	72.067 mi
Registration #11	2019-05-20	81.316 mi
Registration #12	2019-05-20	81.316 mi
Registration #13	2019-05-20	81.316 mi
Registration #14	2019-05-20	81.316 mi
Registration #15	2019-05-20	81.316 mi
Registration #16	2019-05-20	81.316 mi
Registration #17	2019-05-20	81.316 mi
Registration #18	2019-05-20	81.316 mi
Registration #19	2019-05-20	81.316 mi
Registration #20	2019-05-20	81.316 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1447 mm
Length	4581 mm
Wheel base	2760 mm

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	64681130344538