



SV08UJA

report date: 2024-03-28

General information

Make	VOLVO
Model	S40
Colour	Red
Year of manufacture	-
Gearbox	-

Engine & fuel consumption

Fuel type	Petrol
-----------	--------



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-31
Pictures	11
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT #16</b>	2021-08-18 13:16
<b>MOT test number</b>	977387059344
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-08-17
<b>Advice</b>	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Advice</b>	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

<b>MOT #15</b>	2021-08-18 08:57
<b>MOT test number</b>	275077227274
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Nearside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
<b>Advice</b>	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Fail</b>	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
<b>Advice</b>	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Fail</b>	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

<b>MOT #14</b>	2020-09-22 10:42
<b>MOT test number</b>	448437986685
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front gaiter slightly deteriorated
<b>Advice</b>	Rear springs corroded

<b>MOT #13</b>	2019-09-23 10:50
<b>MOT test number</b>	359085082761
<b>Result</b>	✓ Passed

**MOT #12**

2019-09-20 08:44

**MOT test number**

860977555224

**Result****✗ Failed**

**Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Fail** Offside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #11**

2018-09-24 08:49

**MOT test number**

976412203376

**Result****✓ Passed**

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Brake disc worn, pitted or scored, but not seriously weakened all (1.1.14 (a) (ii))

**MOT #10**

2018-01-04 11:31

**MOT test number**

398879462787

**Result****✓ Passed**

**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #9**

2018-01-04 11:31

**MOT test number**

822706971095

**Result****✗ Failed**

**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)

**MOT #8** 2016-12-15 11:50**MOT test number** 752983701152**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2015-12-17 10:33**MOT test number** 324687199344**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #6** 2014-12-30 15:10**MOT test number** 137394064311**Result** ✓ Passed**Notice** Rear exhaust bracket deteriorated but section still secure**MOT #5** 2014-12-30 15:10**MOT test number** 277554864350**Result** ✗ Failed**Notice** Rear exhaust bracket deteriorated but section still secure**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #4** 2013-12-18 16:23**MOT test number** 566222953387**Result** ✓ Passed**MOT #3** 2012-12-19 16:02**MOT test number** 876994952311**Result** ✓ Passed



MOT #2	2012-01-04 11:21
MOT test number	799414602020
Result	✓ Passed
MOT #1	2011-02-11 13:07
MOT test number	358122241035
Result	✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-03-07
Last registration	2021-08-18
Complete history	<a href="#">See info</a>



Registration #1	2008-03-07	22 mi
Registration #2	2011-02-11	24.229 mi
Registration #3	2012-01-04	24.532 mi
Registration #4	2012-12-19	33.414 mi
Registration #5	2013-12-18	44.462 mi
Registration #6	2014-12-30	56.112 mi
Registration #7	2015-12-17	65.871 mi
Registration #8	2016-12-15	74.838 mi
Registration #9	2018-01-04	84.012 mi
Registration #10	2019-01-01	95.000 mi
Registration #11	2019-01-01	95.000 mi
Registration #12	2019-01-01	95.000 mi
Registration #13	2019-01-01	95.000 mi
Registration #14	2019-01-01	95.000 mi
Registration #15	2019-01-01	95.000 mi
Registration #16	2019-01-01	95.000 mi
Registration #17	2019-01-01	95.000 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Additional information

Number of seats	4
Engine number	143891