



report date: 2024-03-28

General information

Make	FORD
Model	MONDEO GHIA TDCI
Colour	Grey
Year of manufacture	2005
Top speed	124 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	128 BHP
Max. torque	330 Nm at 1.800 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	58.9 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 2

Date	2022-01-09
Pictures	3
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

Entry 1

Date	2021-06-13
Pictures	0
Listing price	<a href="#">View report</a>

source: autotrader.co.uk



## MOT history

MOT expiry date	2022-03-11
MOT pass rate	57 %
MOT passed	13
Failed MOT tests	10
Total advice items	34
Total items failed	38

MOT #23 2021-02-19 12:51

MOT test number 779281076614

Result ✓ Passed

Next expiry date 2022-03-11

**Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement d-bush (5.3.4 (a) (i))

**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #22 2021-02-18 11:56

MOT test number 124505233670

Result ✗ Failed

**Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement d-bush (5.3.4 (a) (i))

**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #21 2020-03-12 18:34

MOT test number 484388010462

Result ✓ Passed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #20**

2020-02-19 14:35

**MOT test number**

249449676298

**Result**

✗ Failed

- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Service brake excessively fluctuating (1.2.1 (e))
- Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))
- Fail** Offside Rear Position lamp showing white light to the rear (4.2.3 (a) (ii))
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #19**

2019-01-16 09:24

**MOT test number**

515715585312

**Result**

✓ Passed

- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened both rears (1.1.14 (a) (ii))

**MOT #18**

2018-01-29 16:05

**MOT test number**

226985589712

**Result**

✓ Passed

- Advice** Front brake discs slightly worn
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** E m light on
- Advice** Offside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)

**MOT #17**

2018-01-24 10:54

**MOT test number**

992156054553

**Result****✗ Failed**

- Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)
- Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)
- Advice** Offside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)
- Advice** E m light on
- Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Advice** Front brake discs slightly worn

**MOT #16**

2017-01-09 16:51

**MOT test number**

759431495908

**Result****✓ Passed**

- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #15**

2017-01-04 15:36

**MOT test number**

738551344147

**Result****✗ Failed**

- Fail** Nearside Front Front wheel bearing rough when rotated (2.5.A.2)
- Fail** Offside Front Brake pipe excessively corroded (3.6.B.2c)
- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)
- Fail** Rear front brake excessively fluctuating both (3.7.B.3)
- Fail** Nearside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)
- Fail** Offside Front Front wheel bearing rough when rotated (2.5.A.2)
- Fail** Nearside Front Brake pipe excessively corroded (3.6.B.2c)
- Fail** Front brake excessively fluctuating both (3.7.B.3)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #14**

2016-01-20 15:06

**MOT test number**

186858512893

**Result****✓ Passed**

- Advice** Parking brake lever has little reserve travel (3.1.6b)

**MOT #13**

2016-01-18 13:55

**MOT test number**

596018171617

**Result****✗ Failed**

- Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)
- Fail** Rear wheel bearing has excessive play both (2.6.2)
- Fail** Offside Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)
- Fail** Offside Front front brake excessively fluctuating (3.7.B.3)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)

**MOT #12**

2015-01-14 12:49

**MOT test number**

187954015451

**Result****✓ Passed**

- Notice** E m light on
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #11**

2015-01-12 10:49

**MOT test number**

188712715453

**Result****✗ Failed**

- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Notice** E m light on
- Fail** Parking brake lever has no reserve travel (3.1.6b)
- Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Nearside Rear coil spring broken (2.4.C.1a)

**MOT #10**

2014-01-30 09:07

**MOT test number**

359460634064

**Result**

✓ Passed

- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)

**MOT #9**

2014-01-22 11:24

**MOT test number**

226462224040

**Result**

✗ Failed

- Fail** Nearside Brake pipe excessively corroded (3.6.B.2c)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Fail** Offside Rear Brake pipe excessively corroded (3.6.B.2c)
- Fail** Offside Brake pipe excessively corroded (3.6.B.2c)
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Nearside Rear Brake pipe excessively corroded (3.6.B.2c)

**MOT #8**

2013-01-29 12:40

**MOT test number**

155129923072

**Result**

✓ Passed





<b>MOT #7</b>	2013-01-29 11:58
<b>MOT test number</b>	515059123045
<b>Result</b>	✗ Failed
<b>Fail</b>	Parking brake: efficiency below requirements (3.7.B.7)

<b>MOT #6</b>	2013-01-21 11:21
<b>MOT test number</b>	625201523073
<b>Result</b>	✗ Failed
<b>Fail</b>	Offside Rear rear parking brake recording little or no effort (3.7.B.6a)
<b>Advice</b>	Brake pipe slightly corroded (3.6.B.2c)
<b>Fail</b>	Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)
<b>Notice</b>	Engine undercover loose
<b>Fail</b>	Parking brake: efficiency below requirements (3.7.B.7)

<b>MOT #5</b>	2011-11-30 14:15
<b>MOT test number</b>	799564331317
<b>Result</b>	✓ Passed

<b>MOT #4</b>	2011-11-30 10:13
<b>MOT test number</b>	966694231389
<b>Result</b>	✗ Failed
<b>Fail</b>	Rear wheel bearing rough when rotated (2.6.1)
<b>Fail</b>	Brake disc in such a condition that it is seriously weakened (3.5.1i)

<b>MOT #3</b>	2010-11-30 11:53
<b>MOT test number</b>	921584430356
<b>Result</b>	✓ Passed



MOT #2	2009-10-05 10:37
MOT test number	841918679225
Result	✓ Passed

MOT #1	2008-10-13 14:34
MOT test number	303937288436
Result	✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-28
Current registration	*****
Plate since	2019-06-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2005-10-28
Last registration	2021-02-19
Complete history	<a href="#">See info</a>



Registration #1	2005-10-28	15 mi
Registration #2	2008-10-13	32.096 mi
Registration #3	2009-10-05	38.422 mi
Registration #4	2010-11-30	47.291 mi
Registration #5	2011-11-30	54.301 mi
Registration #6	2011-11-30	54.301 mi
Registration #7	2013-01-21	62.741 mi
Registration #8	2013-01-29	62.759 mi
Registration #9	2013-01-29	62.769 mi
Registration #10	2014-01-22	70.110 mi
Registration #11	2014-01-30	70.110 mi
Registration #12	2015-01-12	77.774 mi
Registration #13	2015-01-14	77.840 mi
Registration #14	2015-01-20	78.000 mi
Registration #15	2015-01-20	78.000 mi
Registration #16	2015-01-20	78.000 mi
Registration #17	2015-01-20	78.000 mi
Registration #18	2015-01-20	78.000 mi
Registration #19	2015-01-20	78.000 mi
Registration #20	2015-01-20	78.000 mi
Registration #21	2015-01-20	78.000 mi
Registration #22	2015-01-20	78.000 mi
Registration #23	2015-01-20	78.000 mi
Registration #24	2015-01-20	78.000 mi
Registration #25	2015-01-20	78.000 mi
Registration #26	2015-01-20	78.000 mi

**More info** >





Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1958 mm
Height	1429 mm
Length	4731 mm
Wheel base	2754 mm
Kerb weight	1531 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	4T10232
---------------	---------