



report date: 2024-03-29

General information

|                     |                  |
|---------------------|------------------|
| Make                | VOLVO            |
| Model               | S40 SE LUX D S40 |
| Colour              | Gold             |
| Year of manufacture | -                |
| Top speed           | 127 mph          |
| 0 - 60 mph          | 8.9 seconds      |
| Gearbox             | 6 speed Manual   |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 134 BHP             |
| Max. torque             | 320 Nm at 2.000 rpm |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 37.2 mpg            |
| Consumption extra urban | 62.8 mpg            |
| Consumption combined    | 50.4 mpg            |



LABEL UNKNOWN



Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2022-01-06                  |
| Pictures      | 2                           |
| Listing price | <a href="#">View report</a> |



source: autotrader.co.uk

**MOT history**

|                         |   |
|-------------------------|---|
| <b>MOT #16</b>          | 2023-02-09 13:16  |
| <b>MOT test number</b>  | 210636066594  |
| <b>Result</b>           | ✓ Passed  |
| <b>Next expiry date</b> | 2024-02-08  |
| <b>Advice</b>           | Handbrake need adjustment                                   |
| <b>Advice</b>           | Offside Front Wheel bearing has slight play (5.1.3 (a) (i)) |

|                        |                  |
|------------------------|------------------|
| <b>MOT #15</b>         | 2022-01-18 14:28 |
| <b>MOT test number</b> | 780004903599     |
| <b>Result</b>          | ✓ Passed         |

|                        |                                 |
|------------------------|---------------------------------|
| <b>MOT #14</b>         | 2021-02-25 16:37                |
| <b>MOT test number</b> | 478211649154                    |
| <b>Result</b>          | ✓ Passed                        |
| <b>Advice</b>          | Rear exhaust box cover corroded |

|                        |  |
|------------------------|--|
| <b>MOT #13</b>         | 2021-02-25 15:25   |
| <b>MOT test number</b> | 422615664994   |
| <b>Result</b>          | ✗ Failed   |
| <b>Fail</b>            | Nearside Front Suspension arm pin or bush excessively worn wishbone bush (5.3.4 (a) (i)) |
| <b>Fail</b>            | Offside Rear Direction indicator incorrect colour (4.4.3 (a))                            |
| <b>Fail</b>            | Nearside Front Position lamp not working (4.2.1 (a) (ii))                                |
| <b>Fail</b>            | Nearside Rear Direction indicator incorrect colour (4.4.3 (a))                           |

|                        |                  |
|------------------------|------------------|
| <b>MOT #12</b>         | 2020-02-29 11:17 |
| <b>MOT test number</b> | 689574446856     |
| <b>Result</b>          | ✓ Passed         |

**MOT #11** 2019-02-27 11:33**MOT test number** 163264637420**Result** ✓ Passed**MOT #10** 2019-02-25 11:18**MOT test number** 695623395099**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Rear Position lamp not working (4.2.1 (a))**MOT #9** 2018-02-23 15:06**MOT test number** 512563484637**Result** ✓ Passed**Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #8** 2016-06-07 15:21**MOT test number** 249458002125**Result** ✓ Passed**Advice** Rear silencer outer casing corroded**Advice** All brake discs very rusty

**MOT #7** 2016-06-07 11:20**MOT test number** 279012821637**Result** ✗ Failed**Advice** Engine leaking oil**Fail** Offside Headlamp aim too low wont adjust (1.8)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Rear silencer outer casing corroded**Fail** Nearside Headlamp aim too low wont adjust (1.8)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** All brake discs very rusty**MOT #6** 2015-03-03 12:25**MOT test number** 886852365016**Result** ✓ Passed**MOT #5** 2014-03-25 15:54**MOT test number** 917354584035**Result** ✓ Passed**MOT #4** 2014-03-25 09:41**MOT test number** 798944484067**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #3** 2013-04-03 09:30**MOT test number** 199523193444**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)



|                 |                  |
|-----------------|------------------|
| MOT #2          | 2012-03-20 15:40 |
| MOT test number | 648880782052     |
| Result          | ✓ Passed         |

|                 |                  |
|-----------------|------------------|
| MOT #1          | 2011-06-02 11:36 |
| MOT test number | 429093851102     |
| Result          | ✓ Passed         |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,299 |
| Auction value               | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |            |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration |            |
| Plate since          | 2024-03-29 |
| Current registration |            |
| Plate since          | 2024-03-29 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 18                       |
| First mileage registration | 2008-06-06               |
| Last registration          | 2023-02-09               |
| Complete history           | <a href="#">See info</a> |



|                  |            |            |
|------------------|------------|------------|
| Registration #1  | 2008-06-06 | 24 mi      |
| Registration #2  | 2011-06-02 | 37.464 mi  |
| Registration #3  | 2012-03-20 | 42.658 mi  |
| Registration #4  | 2013-04-03 | 63.368 mi  |
| Registration #5  | 2014-03-25 | 81.143 mi  |
| Registration #6  | 2014-03-25 | 81.143 mi  |
| Registration #7  | 2015-03-03 | 105.487 mi |
| Registration #8  | 2016-06-07 | 109.677 mi |
| Registration #9  | 2016-06-07 | 109.677 mi |
| Registration #10 | 2017-06-07 | 109.677 mi |
| Registration #11 | 2017-06-07 | 109.677 mi |
| Registration #12 | 2017-06-07 | 109.677 mi |
| Registration #13 | 2017-06-07 | 109.677 mi |
| Registration #14 | 2017-06-07 | 109.677 mi |
| Registration #15 | 2017-06-07 | 109.677 mi |
| Registration #16 | 2017-06-07 | 109.677 mi |
| Registration #17 | 2017-06-07 | 109.677 mi |
| Registration #18 | 2017-06-07 | 109.677 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1770 mm |
| Height              | 1454 mm |
| Length              | 4476 mm |
| Wheel base          | 2640 mm |
| Kerb weight         | 1457 kg |
| Max. allowed weight | 1940 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 52 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 4                |
| Number of seats    | 5                |

|                        |        |
|------------------------|--------|
| <b>Number of axles</b> | 2      |
| <b>Engine number</b>   | 411629 |