



General information

Make	VOLKSWAGEN
Model	BEETLE LUNA 8V
Colour	Red
Year of manufacture	2006
Top speed	111 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	147 Nm at 3.800 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history

Entry 2

Date	2022-07-25
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2021-06-13
Pictures	2
Listing price	View report



source: [yesauto.com](#)



MOT history

MOT expiry date	2024-08-02
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	34
Total items failed	2

MOT #18	2023-08-03 15:58
---------	------------------

MOT test number	920485716435
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-08-02
------------------	------------

- Advice** Exhaust emits blue smoke during acceleration (8.2.1.2 (g))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3 mm (5.2.3 (e))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Inner rear bush (5.3.4 (a) (i))
- Advice** Offside wiper arm well worn
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 3 mm (5.2.3 (e))

**MOT #17**

2023-08-03 11:50

MOT test number

427499176786

Result**✗ Failed**

- MAJOR** Nearside Front passenger door cannot be opened from inside the vehicle (6.2.3 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3 mm (5.2.3 (e))
- Advice** Exhaust emits blue smoke during acceleration (8.2.1.2 (g))
- Advice** Offside wiper arm well worn
- MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 3 mm (5.2.3 (e))
- MAJOR** Nearside Rear Direction indicator not working (4.4.1 (a) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Inner rear bush (5.3.4 (a) (i))

MOT #16

2022-04-07 15:21

MOT test number

531924924212

Result**✓ Passed****MOT #15**

2022-03-24 14:52

MOT test number

906305942653

Result**✗ Failed**

- MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge split and perishing (5.2.3 (e))

**MOT #14** 2020-08-19 14:07**MOT test number** 227855229255**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2019-04-01 15:49**MOT test number** 991967058734**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2018-04-04 15:51**MOT test number** 839596020549**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #11** 2017-03-28 14:35**MOT test number** 490475188785**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #10** 2016-03-24 15:58**MOT test number** 859375604146**Result** ✓ Passed**MOT #9** 2015-03-31 17:11**MOT test number** 395910295034**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2014-03-31 15:23**MOT test number** 355500194046**Result** ✓ Passed**Notice** O/s/f brake disc wearing thin**MOT #7** 2014-03-26 15:47**MOT test number** 439935184082**Result** ✗ Failed**Notice** O/s/f brake disc wearing thin**Fail** Offside Rear coil spring broken (2.4.C.1a)**MOT #6** 2013-03-13 16:53**MOT test number** 799922873093**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2013-03-13 14:58**MOT test number** 109572073066**Result** ✗ Failed**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2012-04-05 16:19**MOT test number** 486126292071**Result** ✓ Passed



MOT #3	2011-08-25 12:20
MOT test number	908307031229
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Drivers seat mechanism worn
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2010-08-06 11:50
MOT test number	573078310248
Result	✓ Passed

MOT #1	2009-08-12 15:29
MOT test number	302714729236
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
2 August 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	2 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-09-01
Last registration	2023-08-03
Complete history	See info



Registration #1	2006-09-01	7 mi
Registration #2	2009-08-12	6.871 mi
Registration #3	2010-08-06	9.190 mi
Registration #4	2011-08-25	12.399 mi
Registration #5	2012-04-05	13.085 mi
Registration #6	2013-03-13	18.869 mi
Registration #7	2013-03-13	18.869 mi
Registration #8	2014-03-26	25.629 mi
Registration #9	2014-03-31	25.770 mi
Registration #10	2015-03-31	32.825 mi
Registration #11	2016-03-24	39.384 mi
Registration #12	2016-03-24	39.384 mi
Registration #13	2016-03-24	39.384 mi
Registration #14	2016-03-24	39.384 mi
Registration #15	2016-03-24	39.384 mi
Registration #16	2016-03-24	39.384 mi
Registration #17	2016-03-24	39.384 mi
Registration #18	2016-03-24	39.384 mi
Registration #19	2016-03-24	39.384 mi
Registration #20	2016-03-24	39.384 mi
Registration #21	2016-03-24	39.384 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2515 mm
Kerb weight	1314 kg
Max. allowed weight	1680 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BFS 051011