



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D R-DESIGN SE
Colour	Grey
Year of manufacture	2009
Top speed	124 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	157 g/km
CO2 label	G





## MOT history

MOT expiry date	2021-07-21
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	20
Total items failed	7

MOT #16	2020-06-23 09:53
MOT test number	751935148731
Result	✓ Passed
Next expiry date	2021-07-21
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #15	2020-06-23 09:53
MOT test number	886668104630
Result	✗ Failed
Pass with rectification	Offside Rear Road wheel fixing missing (5.2.1 (a) (i))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #14	2019-07-22 14:20
MOT test number	170740315510
Result	✓ Passed

MOT #13	2019-07-22 14:20
MOT test number	569255540188
Result	✗ Failed
Pass with rectification	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

**MOT #12** 2018-07-09 13:46**MOT test number** 376237659118**Result** ✓ Passed**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear All direction indicators slightly discoloured (4.4.3 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear All direction indicators slightly discoloured (4.4.3 (a))**MOT #11** 2017-07-10 15:00**MOT test number** 716749315014**Result** ✓ Passed**Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**MOT #10** 2017-07-08 11:09**MOT test number** 183332432180**Result** ✗ Failed**Fail** Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #9** 2016-07-11 15:04**MOT test number** 109023503900**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2016-01-04 21:18**MOT test number** 706639942365**Result** ✓ Passed**MOT #7** 2015-07-11 17:13**MOT test number** 726922395144**Result** ✓ Passed**MOT #6** 2015-07-11 17:13**MOT test number** 225252095406**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high and too far to the left. (1.8)**MOT #5** 2015-01-12 19:39**MOT test number** 167042815068**Result** ✓ Passed**MOT #4** 2014-07-12 13:15**MOT test number** 518173694181**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)



<b>MOT #3</b>	2014-01-14 17:48
<b>MOT test number</b>	226674414053
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Brake pad(s) wearing thin (3.5.1g)

<b>MOT #2</b>	2013-07-15 17:16
<b>MOT test number</b>	127016093148
<b>Result</b>	✓ Passed

<b>MOT #1</b>	2012-09-03 15:41
<b>MOT test number</b>	548007742254
<b>Result</b>	✓ Passed
<b>Notice</b>	Engine covers fitted obscuring some components in the engine bay
<b>Notice</b>	Under-trays fitted obscuring some underside components
<b>Notice</b>	Front number plate cracked



## Tax &amp; MOT check

**×**  
**Untaxed**

**Tax expired:**  
23 December 2020

**×**  
**MOT**

**Expired:**  
21 July 2021

**Tax status**

Expired at 23 December 2020

**Days left**

1224 days too late

**MOT expiry date**

21 July 2021

**Full MOT history**[See MOT history](#)

## Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>LR59TWW</b>
Plate since	2019-09-29
Current registration	<b>LR59TWW</b>
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-09-23
Last registration	2020-06-23
Complete history	<a href="#">See info</a>



Registration #1	2009-09-23	16 mi
Registration #2	2012-09-03	12.168 mi
Registration #3	2013-07-15	14.751 mi
Registration #4	2014-01-14	26.726 mi
Registration #5	2014-07-12	61.897 mi
Registration #6	2015-01-12	87.670 mi
Registration #7	2015-07-11	109.558 mi
Registration #8	2016-01-04	138.752 mi
Registration #9	2016-06-23	161.557 mi
Registration #10	2017-06-23	184.362 mi
Registration #11	2018-06-23	207.167 mi
Registration #12	2019-06-23	229.972 mi
Registration #13	2020-06-23	252.777 mi
Registration #14	2021-06-23	275.582 mi
Registration #15	2022-06-23	298.387 mi
Registration #16	2023-06-23	321.192 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1737 kg
Max. allowed weight	2270 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	613349
---------------	--------