





report date: 2024-03-28

General information

Make	PEUGEOT
Model	5008 HDI SPORT
Colour	Red
Year of manufacture	2011
Top speed	115 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	62.8 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/12



Internet history


Entry 2

Date 2021-07-25

Pictures 15

Listing price <u>View report</u>









source: yesauto.com


Entry 1

Date	2021-07-21

Pictures 6

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-06-14
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	17
Total items failed	4

MOT #13	2023-06-14 10:43
MOT test number	136094368538
Result	✓ Passed
Next expiry date	2024-06-14

MOT #12	2022-06-15 11:39
MOT test number	616265812728
Result	✓ Passed

MOT #11	2021-07-28 07:56
MOT test number	405782732390
Result	✓ Passed

MOT #10	2020-07-28 12:34
MOT test number	316932092900
Result	✓ Passed

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

CarCheck.co.uk page 3/12



Result

FL11LXF report date: 2024-03-28

Passed

MOT #9 2020-07-28 10:21

MOT test number 631829285217

Result X Failed

Fail Offside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #8 2019-06-21 10:23

MOT test number 215001737073

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge perishing (5.2.3 (e))

MOT #7 2019-06-20 07:56

MOT test number 181363138374

Result X Failed

Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Nearside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge perishing (5.2.3 (e))

MOT #6 2018-07-11 08:12

MOT test number 735022260052

Result

Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))

CarCheck.co.uk page 4/12



MOT #5

MOT test number

Result

Advice Offside Front tyre edges worn

Advice Nearside Front tyre edges worn

MOT #4

MOT test number

Result

Advice Nearside Rear tyre starting to perish

2016-07-20 08:17

541507049199

✓ Passed

MOT test number

Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Rear tyres are perishing

MOT #2	2014-08-05 07:56
MOT #2	2014-08-03 07.30
MOT test number	375307414466
Result	✓ Passed
MOT #1	2014-04-10 16:01
MOT test number	168840404197
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	14 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	NIE NIE NIE NIE NIE NIE NIE NIE NIE NIE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-04-13
Last registration	2023-06-14
Complete history	See info



Registration #1	2011-04-13	11 mi
Registration #2	2014-04-10	14.798 mi
Registration #3	2014-08-05	15.661 mi
Registration #4	2015-07-24	23.915 mi
Registration #5	2016-07-20	33.371 mi
Registration #6	2017-07-19	43.232 mi
Registration #7	2018-07-11	52.464 mi
Registration #8	2019-06-20	63.272 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		10.777 es

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	89%
Children	79%
Pedestrian	37%
Safety systems	97%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2118 mm
Height	1638 mm
Length	4530 mm
Wheel base	2727 mm
Kerb weight	1577 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/1

Number of axles 2

Engine number JBER3024943