



General information

Make	VOLKSWAGEN
Model	CRAFTER CR35 TDI H/R P/V
Colour	White
Year of manufacture	2012
Gearbox	6 speed Manual

Engine & fuel consumption

Power	141 BHP
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-09-09
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	11
Total items failed	5

MOT #5	2023-08-23 16:12
MOT test number	618997656081
Result	✓ Passed
Next expiry date	2024-09-09

MOT #4	2022-09-08 16:10
MOT test number	503187544454
Result	✓ Passed

- Advice

Oil leak, but not excessive engine (8.4.1 (a) (i))
- Advice

Front Brake disc worn, pitted or scored, but not seriously weakened inner surfaces (1.1.14 (a) (ii))
- Minor

Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

**MOT #3**

2022-09-05 15:13

MOT test number

314627533266

Result

✗ Failed

- Fail** Nearside Side repeater not working (4.4.1 (a) (ii))
- Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened inner surfaces (1.1.14 (a) (ii))
- Minor** Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))
- Fail** Front Passenger's seat with a defective structure bolt missing out of seat back support (6.2.6 (a) (i))
- Fail** Rear Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))
- Fail** Exhaust has a major leak of exhaust gases from dpf to backbox split along pipe. (6.1.2 (a))
- Fail** Front Driver's seat with a defective structure bolt missing out of seat back support (6.2.5 (a) (i))

MOT #2

2021-09-10 16:46

MOT test number

615103571373

Result

✓ Passed

- Advice** Park brake has limited reserve travel
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #1

2015-03-30 15:44

MOT test number

318969785068

Result

✓ Passed

- Notice** Oil leak
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
9 September 2024

Tax status		Valid until 1 September
Days left		125
MOT expiry date		9 September 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXX
Plate since	2024-03-28
Current registration	 XXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2012-04-12
Last registration	2023-08-23
Complete history	See info



Registration #1	2012-04-12	24 mi
Registration #2	2015-03-30	104.729 mi
Registration #3	2019-09-10	138.545 mi
Registration #4	2021-09-10	138.545 mi
Registration #5	2021-09-10	138.545 mi
Registration #6	2021-09-10	138.545 mi
Registration #7	2021-09-10	138.545 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	CKUC006865