



report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT 290 LR P/V
Colour	White
Year of manufacture	2015
Top speed	98 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 kW / 155 HP / 98 BHP
Max. torque	330 Nm at 1.600 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	40.4 mpg
CO2 emission	186 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-01-31
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-09-19
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	12
Total items failed	1

MOT #8	2023-09-20 13:11
MOT test number	888604062888
Result	✓ Passed
Next expiry date	2024-09-19
Advice	Offside Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Brake pipes greased

MOT #7	2022-06-30 11:13
MOT test number	258572212435
Result	✓ Passed

MOT #6	2021-07-12 11:36
MOT test number	538004783022
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #5	2021-07-06 08:42
MOT test number	603713889896
Result	✓ Passed

**MOT #4** 2020-07-13 15:06**MOT test number** 180542435653**Result** ✓ Passed**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #3** 2020-07-13 07:54**MOT test number** 565295761763**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #2** 2019-08-19 08:58**MOT test number** 242415639383**Result** ✓ Passed**Advice** Offside Front Brake pipe corroded, covered in grease or other material slight corrosion (1.1.11 (c))**Advice** Offside Front Power steering pipe/hose slightly corroded at rack (2.1.5 (g) (i))**Advice** Rear service brake imbalance 28%**MOT #1** 2018-08-03 08:45**MOT test number** 213314716330**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
19 September 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	19 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-08-06
Last registration	2023-09-20
Complete history	See info



Registration #1	2015-08-06	28 mi
Registration #2	2018-08-03	67.975 mi
Registration #3	2019-08-19	90.139 mi
Registration #4	2020-07-13	107.713 mi
Registration #5	2020-07-13	107.713 mi
Registration #6	2020-07-13	107.713 mi
Registration #7	2020-07-13	107.713 mi
Registration #8	2020-07-13	107.713 mi
Registration #9	2020-07-13	107.713 mi
Registration #10	2020-07-13	107.713 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	90%
Pedestrian	48%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	2272 mm
Height	2020 mm
Length	4972 mm
Wheel base	3300 mm
Kerb weight	1817 kg
Max. allowed weight	2900 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3

Number of axles	2
Engine number	FY82049