



report date: 2024-03-29

General information

Make	FIAT
Model	DOBLO 16V MULTIJET
Colour	White
Year of manufacture	2016
Top speed	98 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	65.7 mpg
Consumption combined	57.6 mpg
CO2 emission	133 g/km
CO2 label	E





Internet history

Entry 2

Date	2021-10-29
Pictures	15
Listing price	View report



source: [yesauto.com](#)

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-02-01
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	3
Total items failed	7

MOT #7	2024-02-02 16:17
MOT test number	421869932116
Result	✓ Passed
Next expiry date	2025-02-01

MOT #6	2024-02-01 13:14
MOT test number	748846105740

Result	✗ Failed
--------	----------

Pass with rectification Offside Driver's seat fore and aft adjustment mechanism not functioning as intended. (6.2.5 (b) (i))

Pass with rectification Nearside Headlamp aim too high (4.1.2 (a))

Fail Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

Fail Brake pedal anti-slip provision missing (1.1.2 (c))

Pass with rectification Offside Headlamp aim too high (4.1.2 (a))

Fail Offside Front Coil spring fractured or broken broken (5.3.1 (b) (i))

MOT #5	2022-09-12 11:16
--------	------------------

MOT test number	786039775912
-----------------	--------------

Result	✓ Passed
--------	----------

**MOT #4** 2022-09-12 11:16**MOT test number** 965781094636**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #3** 2021-09-08 14:19**MOT test number** 829718058011**Result** ✓ Passed**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing in tread (5.2.3 (d) (ii))**MOT #2** 2020-10-01 14:13**MOT test number** 796976363532**Result** ✓ Passed**MOT #1** 2019-10-15 13:37**MOT test number** 628568237920**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
1 February 2025

Tax status		Valid until 1 February
Days left		277
MOT expiry date		1 February 2025
Full MOT history		See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-12-01
Last registration	2024-02-02
Complete history	See info



Registration #1	2016-12-01	9 mi
Registration #2	2019-10-15	52.937 mi
Registration #3	2020-10-01	61.585 mi
Registration #4		
Registration #5	2021-09-08	65.811 mi
Registration #6		
Registration #7		
Registration #8		
Registration #9		
Registration #10		

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	5903096