



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	TIGRA 16V EXCLUSIV
Colour	Red
Year of manufacture	2006
Top speed	112 mph
0 - 60 mph	12.4 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	89 BHP
Max. torque	125 Nm at 4.000 rpm
Engine capacity	1.364 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.9 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.3 mpg
CO2 emission	146 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-06-18
Pictures	30
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-10-17
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	25
Total items failed	6

MOT #19	2023-09-26 13:23
MOT test number	197479943328
Result	✓ Passed
Next expiry date	2024-10-17
Advice	Offside Rear Tyre slightly damaged/cracking or perishing slight cracking (5.2.3 (d) (ii))

MOT #18	2022-10-18 12:55
MOT test number	527106748790
Result	✓ Passed

MOT #17	2022-10-18 12:55
MOT test number	231267080205
Result	✗ Failed
Pass with rectification	Offside Front Service brake excessively fluctuating (1.2.1 (e))
Pass with rectification	Nearside Front Service brake excessively fluctuating (1.2.1 (e))

MOT #16	2021-10-05 14:22
MOT test number	406341520414
Result	✓ Passed
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #15**

2021-10-05 09:36

**MOT test number**

475748875708

**Result**

✗ Failed

**Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))**Fail** Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #14**

2020-10-12 15:01

**MOT test number**

649895763652

**Result**

✓ Passed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Nail in tyre**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #13**

2019-09-26 15:53

**MOT test number**

302533579384

**Result**

✓ Passed

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened inner surfaces (1.1.14 (a) (ii))**MOT #12**

2019-09-26 10:44

**MOT test number**

581427672330

**Result**

✗ Failed

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Rear Brakes imbalanced across an axle 49% (1.2.1 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened inner surfaces (1.1.14 (a) (ii))

**MOT #11** 2018-09-28 08:28**MOT test number** 210474522337**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #10** 2017-10-04 07:39**MOT test number** 932227028232**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Anti-roll bar ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Central Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #9** 2016-08-24 07:49**MOT test number** 976433045014**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8** 2016-08-24 07:49**MOT test number** 283214980223**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #7** 2015-09-15 08:46**MOT test number** 454731809937**Result** ✓ Passed**MOT #6** 2014-09-18 09:56**MOT test number** 218061064200**Result** ✓ Passed**MOT #5** 2013-08-12 11:50**MOT test number** 167544623253**Result** ✓ Passed**Notice** Offside outer cv boot clip weak**Notice** Rear tyres starting to perish between treads and bad stone cuts**MOT #4** 2012-08-09 13:17**MOT test number** 627342822237**Result** ✓ Passed**Notice** Cuts in treads of o/s/r tyre**Notice** Cut in treads of o/s/f tyre**MOT #3** 2011-07-14 10:51**MOT test number** 749445691186**Result** ✓ Passed**MOT #2** 2010-08-05 11:41**MOT test number** 201707310209**Result** ✓ Passed



MOT #1	2009-07-13 14:37
MOT test number	224044299110
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 June 2024

✓  
**MOT**  
  
Expires:  
17 October 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	17 October 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXX
XXXXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-29
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-08-11
Last registration	2023-09-26
Complete history	<a href="#">See info</a>



Registration #1	2006-08-11	21 mi
Registration #2	2009-07-13	10.177 mi
Registration #3	2010-08-05	13.530 mi
Registration #4	2011-07-14	16.095 mi
Registration #5	2012-08-09	18.937 mi
Registration #6	2013-08-12	21.086 mi
Registration #7	2014-09-18	24.217 mi
Registration #8	2015-09-15	27.672 mi
Registration #9	2016-08-24	31.620 mi
Registration #10	2016-08-24	31.620 mi
Registration #11	2017-10-04	36.233 mi
Registration #12	2019-09-26	39.337 mi
Registration #13	2019-09-26	39.337 mi
Registration #14	2019-09-26	39.337 mi
Registration #15	2019-09-26	39.337 mi
Registration #16	2019-09-26	39.337 mi
Registration #17	2019-09-26	39.337 mi
Registration #18	2019-09-26	39.337 mi
Registration #19	2019-09-26	39.337 mi
Registration #20	2019-09-26	39.337 mi
Registration #21	2019-09-26	39.337 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1905 mm
Height	1364 mm
Length	3921 mm
Wheel base	2491 mm
Kerb weight	1185 kg
Max. allowed weight	1475 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Engine number	19GK2653