





report date: 2024-03-28

General information

Make	AUDI
Model	A6 TDI S LINE
Colour	Black
Year of manufacture	2008
Top speed	130 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 сс
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.1 mpg
CO2 emission	162 g/km
CO2 label	G



CarCheck.co.uk page 1/12



SP58ZKF
report date: 2024-03-28

MOT history

MOT expiry date	2025-01-21
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	20
Total items failed	8

MOT #16	2024-01-22 14:58
MOT test number	503200571087
Result	✓ Passed
Next expiry date	2025-01-21
Advice Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cord	s (5.2.3 (d) (i))
Advice Rear Bumper diffuser slightly insecure	
Advice Rear Inner Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))	
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in exces rear arm inner bush (5.3.4 (a) (i))	sive movement
Advice Tyre slightly damaged/cracking or perishing All 4 tyres (5.2.3 (d) (ii))	
Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorate	ed (6.1.7 (g) (i))
Advice Front Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excess (5.3.4 (a) (i))	ive movement
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT test number
987680352840

Result

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #14 2022-09-21 08:46 **MOT** test number 386211089035 Result × Failed Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a)) Pass with rectification Nearside Headlamp aim too high (4.1.2 (a)) **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) **Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) Fail Offside Headlamp insecure (4.1.1 (c)) Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) Minor (i))

(1))	
MOT #13	2021-08-21 09:48
MOT test number	117740818041
Result	✓ Passed
MOT #12	2020-10-23 15:13
MOT test number	332888568555
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #11		2020-10-23 15:13
MOT test number		249797448314
Result		× Failed
Pass with rectification	Nearside Rear Position lamp lens seriously defective (4.2.1 (b))	

MOT #10	2019-03-26 12:02
MOT test number	366652084666
Result	✓ Passed
MOT #9	2018-02-24 15:03
MOT test number	580381852918
Result	✓ Passed
MOT #8	2017-03-22 17:06
MOT test number	861192333231
Result	✓ Passed
MOT #7	2016-04-26 13:39
MOT test number	587799817959
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)	

MOT #6	2014-10-30 14:30
MOT test number	349573104390
Result	✓ Passed
MOT #5	2013-10-12 11:34
MOT test number	408785783275
Result	√ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28



Pass with rectification	Offside Headlamp not working on dipped beam (1.7.5a)	
	·	
MOT #3		2012-10-29 16:12
MOT test number		888263702392
Result		✓ Passed
MOT #2		2011-10-21 16:33
MOT test number		397554891469
Result		✓ Passed
MOT #1		2011-10-07 12:15
MOT test number		875400381297
Result		🗙 Failed
Advice Offside Front Ty	re worn close to the legal limit (4.1.E.1)	

Fail Nearside Front Front wheel bearing rough when rotated (2.5.A.2)

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	21 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

More info >

Owner history	
For how long did the current and previous owner(s) have this AUDI? How many owners of Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	
Current registration	NK SIN
Plate since	
Current registration	UK UK
Plate since	

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-09-30
Last registration	2024-01-22
Complete history	See info



Registration #1	2008-09-30	18 mi
Registration #2	2011-10-07	61.153 mi
Registration #3	2011-10-21	61.620 mi
Registration #4	2012-10-29	79.739 mi
Registration #5	2013-10-12	97.215 mi
Registration #6	2014-10-30	115.109 mi
Registration #7	2016-04-26	132.204 mi
Registration #8	2017-03-22	138.627 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		10.777 mg

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1855 mm
Height	1463 mm
Length	4933 mm
Wheel base	2843 mm
Kerb weight	1610 kg
Max. allowed weight	2240 kg

Additional information

Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2

Engine number BRE 176832