



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX35 CRDI SE
Colour	Grey
Year of manufacture	2014
Top speed	108 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	58.9 mpg
Consumption combined	54.3 mpg
CO2 emission	139 g/km
CO2 label	E






Internet history

Entry 2

Date	2021-07-25
Pictures	50
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-07-23
Pictures	50
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-31
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	59
Total items failed	0

MOT #92023-08-01 15:58

MOT test number455852823505

Result✓ Passed

Next expiry date2024-07-31

- Advice**Central Rear Child Seat fitted not allowing full inspection of adult belt
- Advice**Rear Registration plate insecure but not likely to fall off (0.1 (a))
- Advice**Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice**Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice**Offside Front Fog lamp not working
- Advice**Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Minor**Offside Headlamp reflector slightly defective (4.1.1 (b) (i))
- Advice**Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice**Amber TPMS light is on
- Minor**Nearside Side repeater with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))
- Advice**Clutch hydraulic pipe leaking



MOT #8

2023-07-25 10:02

MOT test number

957485553300

Result		✗ Failed
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice	Amber TPMS light is on	
Advice	Clutch hydraulic pipe leaking	
MAJOR	Front Registration plate inscription illegible (0.1 (b))	
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Minor	Offside Headlamp reflector slightly defective (4.1.1 (b) (i))	
MAJOR	Brake hydraulic reservoir cap missing (1.1.10 (e))	
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice	Offside Front Fog lamp not working	
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor	Nearside Side repeater with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))	
Advice	Rear Registration plate insecure but not likely to fall off (0.1 (a))	
Advice	Central Rear Child Seat fitted not allowing full inspection of adult belt	

**MOT #7**

2022-07-25 09:38

MOT test number

470220577307

Result

✓ Passed

- Advice** Amber TPMS light on dash
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Fog lamp not working
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt

MOT #6

2021-07-26 15:16

MOT test number

945749288932

Result

✓ Passed

- Advice** Front Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened disc (1.1.14 (a) (ii))
- Advice** Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

**MOT #5**

2020-07-17 09:31

MOT test number

153290286059

Result

✓ Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Wearing on inner segment (5.2.3 (e))
- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing Perishing (5.2.3 (d) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Emissions too low to read
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Wearing on inner segment (225/60/17) (5.2.3 (e))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2.5mm and perishing (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #4

2019-07-19 10:05

MOT test number

697391201091

Result

✓ Passed

- Advice** Puncture light on
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear tyres starting to wear close to tread wear bars

**MOT #3** 2019-07-19 08:27**MOT test number** 635415010957**Result** ✗ Failed

- Advice** Child Seat fitted not allowing full inspection of adult belt
- MAJOR** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Puncture light on
- MAJOR** Nearside Headlamp not working on main beam (4.1.1 (a) (ii))
- Advice** Nail in offside front tyre
- Advice** Rear tyres starting to wear close to tread wear bars
- MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #2 2018-07-18 09:17**MOT test number** 700206872659**Result** ✓ Passed

- Advice** Nearside Rear Nail in tyre
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #1 2017-06-28 12:10**MOT test number** 730016467994**Result** ✓ Passed

- Advice** WINDSCREEN DAMAGED OUTSIDE DRIVER VIEW



Tax & MOT check

X

Untaxed

Tax expired:
12 January 2024

✓

MOT

Expires:
31 July 2024

Tax status	Expired at 12 January 2024
Days left	109 days too late
MOT expiry date	31 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-07-19
Last registration	2023-08-01
Complete history	See info



Registration #1	2014-07-19	16 mi
Registration #2	2017-06-28	46.283 mi
Registration #3	2018-07-18	54.346 mi
Registration #4	2019-07-19	61.527 mi
Registration #5	2019-07-19	61.527 mi
Registration #6	2020-07-17	65.122 mi
Registration #7	2020-07-17	65.122 mi
Registration #8	2020-07-17	65.122 mi
Registration #9	2020-07-17	65.122 mi
Registration #10	2020-07-17	65.122 mi
Registration #11	2020-07-17	65.122 mi
Registration #12	2020-07-17	65.122 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FDEZ258681