



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 COUPE CABRIOLET S
Colour	Silver
Year of manufacture	-
Top speed	117 mph
0 - 60 mph	12.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	147 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.6 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-28
Pictures	17
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #21</b>	2021-07-30 14:25
<b>MOT test number</b>	807918621932
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-07-29

<b>MOT #20</b>	2021-07-30 12:42
<b>MOT test number</b>	264219013581
<b>Result</b>	✗ Failed
<div><div>Fail</div> Front Exhaust has a major leak of exhaust gases (6.1.2 (a))</div> <div><div>Fail</div> Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))</div> <div><div>Fail</div> Rear Exhaust system insecure (6.1.2 (a))</div>	

<b>MOT #19</b>	2021-01-11 15:44
<b>MOT test number</b>	997399807276
<b>Result</b>	✓ Passed
<div><div>Advice</div> Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))</div>	

<b>MOT #18</b>	2020-05-28 14:12
<b>MOT test number</b>	103837463717
<b>Result</b>	✓ Passed

**MOT #17**

2019-05-02 13:32

**MOT test number**

873417807092

**Result**

✓ Passed

- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing in tread (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** N/sf inner cv boot deteriorated
- Advice** Indicators becoming pale
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Central Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Handbrake efficiency poor

**MOT #16**

2018-09-27 13:25

**MOT test number**

669345087468

**Result**

✓ Passed

- Advice** N/s/r tyre cracked in tread
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** N/s/f tyre wearing unevenly
- Advice** Indicators becoming pale
- Advice** N/s inner cv boot deteriated
- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Handbrake efficiency poor

**MOT #15**

2018-09-21 11:41

**MOT test number**

847753457284

**Result****✗ Failed**

**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Advice** N/s/r tyre cracked in tread

**Fail** Offside Front Seat belt damaged (7.1.2 (b) (i))

**Advice** N/s/f tyre wearing unevenly

**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

**Advice** Indicators becoming pale

**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

**Advice** N/s inner cv boot deteriorated

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Handbrake efficiency poor

**MOT #14**

2017-09-08 11:20

**MOT test number**

317482391626

**Result****✓ Passed**

**Advice** O/s/f seat belt damaged (cut and frayed)

**MOT #13**

2016-08-02 09:48

**MOT test number**

628300307355

**Result****✗ Failed**

- Advice** Drivers door check strap is broken
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Offside Front coil spring broken (2.4.C.1a)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Fail** Offside Rear position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Offside Stop lamp not working (1.2.1b)
- Advice** Front anti-roll bar not positioned correctly but not fowling
- Fail** Offside Front Seat belt cut sufficient to obstruct correct operation of the belt (5.2.2a)
- Advice** Oil leak gearbox
- Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Nearside Stop lamp not working (1.2.1b)



MOT #12

2015-08-04 14:52

MOT test number

349956715281

Result

✓ Passed

- Advice

Rear Brake pad(s) wearing thin (3.5.1g)
- Notice

Oil leak
- Notice

Both front tyres are worn on edges
- Advice

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice

Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice

Front wiper blades smear on screen
- Advice

Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Notice

Play in steering rack inner joint(s)

**MOT #11**

2015-07-31 11:59

**MOT test number**

706202115200

**Result****✗ Failed****Fail** Nearside Front coil spring broken (2.4.C.1a)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Oil leak**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Rear Stop lamp not working (1.2.1b)**Notice** Both front tyres are worn on edges**Fail** Offside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Front wiper blades smear on screen**Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)**Notice** Play in steering rack inner joint(s)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #10**

2014-07-31 12:27

**MOT test number**

786692914288

**Result****✓ Passed****Advice** Nearside Front Steering rack gaiter deteriorated (2.2.D.2d)**Notice** N/s/f wheel arch cover loose





<b>MOT #9</b>	2013-06-27 17:17
<b>MOT test number</b>	259438473128
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

<b>MOT #8</b>	2012-06-25 15:55
<b>MOT test number</b>	845537772187
<b>Result</b>	✓ Passed
<b>Notice</b>	Offside rear underneath support brace corroding
<b>Notice</b>	Nearside front tyre down to 1.6mm in places
<b>Notice</b>	Rear power steering pipes damp
<b>Notice</b>	One high level stop bulb inop

<b>MOT #7</b>	2011-07-06 15:40
<b>MOT test number</b>	836827981118
<b>Result</b>	✓ Passed
<b>Notice</b>	Advise nearside front ABS sensor clip damaged
<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

<b>MOT #6</b>	2011-07-06 09:32
<b>MOT test number</b>	318287181148
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Rear Direction indicators not working (1.4.A.2c)
<b>Fail</b>	Rear All position lamps adversely affected by the operation of another lamp (1.1.A.3f)
<b>Fail</b>	Nearside Rear Stop lamp not working (1.2.1b)
<b>Notice</b>	Advise nearside front ABS sensor clip damaged
<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2010-06-23 13:09**MOT test number** 251004470456**Result** ✓ Passed**Notice** ADVISE ENGINE OIL LEAK**MOT #4** 2009-07-14 14:51**MOT test number** 761755899106**Result** ✓ Passed**MOT #3** 2008-07-15 10:57**MOT test number** 413487098134**Result** ✓ Passed**MOT #2** 2007-07-21 09:12**MOT test number** 383182307229**Result** ✓ Passed**MOT #1** 2006-07-04 09:18**MOT test number** 532715286104**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2002-08-16
Last registration	2021-07-30
Complete history	<a href="#">See info</a>



Registration #1	2002-08-16	28 mi
Registration #2	2006-07-04	21.026 mi
Registration #3	2007-07-21	26.904 mi
Registration #4	2008-07-15	29.658 mi
Registration #5	2009-07-14	31.852 mi
Registration #6	2010-06-23	34.165 mi
Registration #7	2011-07-06	36.432 mi
Registration #8	2011-07-06	36.432 mi
Registration #9	2012-06-25	38.148 mi
Registration #10	2013-06-27	39.904 mi
Registration #11	2014-07-31	43.520 mi
Registration #12	2015-07-31	46.475 mi
Registration #13	2016-06-25	50.000 mi
Registration #14	2017-06-25	53.525 mi
Registration #15	2018-06-25	57.050 mi
Registration #16	2019-06-25	60.575 mi
Registration #17	2020-06-25	64.100 mi
Registration #18	2021-06-25	67.625 mi
Registration #19	2022-06-25	71.150 mi
Registration #20	2023-06-25	74.675 mi
Registration #21	2024-06-25	78.200 mi
Registration #22	2025-06-25	81.725 mi
Registration #23	2026-06-25	85.250 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1673 mm
Height	1373 mm
Length	3835 mm
Wheel base	2442 mm
Kerb weight	1177 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Engine number	FX2J1451317