





report date: 2024-03-28

## General information

Make	VOLKSWAGEN
Model	TOUAREG V6 R-LINE TDI BLUEMOTION TECHN
Colour	Black
Year of manufacture	2017
Top speed	140 mph
0 - 100 km/h	7.3 seconds
0 - 60 mph	7.3 seconds
Gearbox	8 speed automatic

## Engine & fuel consumption

Power	193 kW / 263 HP / 258 BHP
Max. torque	580 Nm at 1.750 rpm
Engine capacity	2.967 сс
Cylinders	6
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	42.8 mpg
CO2 emission	180 g/km
CO2 label	I



CarCheck.co.uk page 1/11



report date: 2024-03-28

## Internet history

## Entry 1

Date 2021-07-28

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-08-22
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	7
Total items failed	4

MOT #8	2023-07-28 13:43
MOT test number	329293994820
Result	✓ Passed
Next expiry date	2024-08-22

MOT #7	2023-07-27 10:26
MOT test number	922421102960
Result	<b>×</b> Failed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #6	2022-08-02 08:34
MOT test number	607842478042
Result	✓ Passed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #5	2021-08-23 10:24
MOT test number	606681443659
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #4 2021-08-13 08:13

**MOT test number** 583665301579

Result X Failed

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2020-11-12 16:13

MOT test number 474780638478

**Result** ✓ Passed

MOT #2 2020-11-12 15:19

**MOT test number** 361142222395

**Result** X Failed

**Advice** Nearside Rear Nail in tyre

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #1** 2020-07-20 06:41

MOT test number 246909271253

**Result** ✓ Passed

Advice COVID-19 6 MONTH EXTENSION

CarCheck.co.uk page 4/11





report date: 2024-03-28

## Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	22 August 2024
Full MOT history	See MOT history

### Tax calculation

-	
Vehicle class	49
Band	J
First licence fee (12 months)	£ 1.040,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 1.565,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	

Category

**Type** 



#### Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

More info >

# Owner history

o which initially	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	
***************************************	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	OK SIES
Plate since	
Current registration	AIR SIE
Plate since	

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

**Contact info** 

More info >

CarCheck.co.uk page 9/11





report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-07-28
Last registration	2023-07-28
Complete history	See info



Registration #1	2017-07-28	12 mi
Registration #2	2020-11-12	45.577 mi
Registration #3	2020-11-12	45.577 mi
Registration #4		11.777 es
Registration #5	2021-08-13	53.075 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	2208 mm
Height	1732 mm
Length	4801 mm
Wheel base	2893 mm
Kerb weight	2085 kg
Max. allowed weight	2880 kg

## Additional information

Fuel tank capacity	85 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack co.uk	nago 11/11

CarCheck.co.uk page 11/11

Number of axles	2
Engine number	CVVA069700