





General information

| Make | VOLKSWAGEN |
|---------------------|-------------------|
| Model | EOS TDI DSG SPORT |
| Colour | Silver |
| Year of manufacture | 2008 |
| Top speed | 126 mph |
| 0 - 60 mph | 10.3 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 138 BHP |
|-------------------------|---------------------|
| Max. torque | 320 Nm at 1.800 rpm |
| Engine capacity | 1.968 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 31.7 mpg |
| Consumption extra urban | 51.4 mpg |
| Consumption combined | 42.2 mpg |
| CO2 emission | 177 g/km |
| CO2 label | I |







| 2021-07-31 |
|-------------|
| 0 |
| View report |
| |
| |
| 2021-07-30 |
| 0 |
| View report |
| |

source: autotrader.co.uk



MOT history

| MOT expiry date | 2024-08-22 |
|--------------------|------------|
| MOT pass rate | 81 % |
| MOT passed | 13 |
| Failed MOT tests | 3 |
| Total advice items | 8 |
| Total items failed | 4 |

| MOT #16 | 2023-08-23 08:27 |
|------------------|------------------|
| MOT test number | 335623412281 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-22 |

| MOT #15 | 2022-05-04 12:01 |
|--|------------------|
| MOT test number | 977082006476 |
| Result | ✓ Passed |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #14 | 2022-05-04 09:47 |
|---|-------------------------|
| MOT test number | 779285065478 |
| Result | 🗙 Failed |
| Fail Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii)) | |
| Fail Nearside Rear Tyre has a lump, caused by separation or partial failure of its stru | ucture (5.2.3 (d) (ii)) |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #13 | 2021-04-29 10:09 |
|-----------------|------------------|
| MOT test number | 379774259052 |
| Result | ✓ Passed |





| MOT #12 | 2020-05-11 11:45 |
|--|------------------|
| MOT test number | 338394307549 |
| Result | Passed |
| | |
| MOT #11 | 2019-03-14 09:52 |
| MOT test number | 161780789607 |
| Result | ✓ Passed |
| | |
| MOT #10 | 2018-03-14 15:33 |
| MOT test number | 964933575005 |
| Result | ✓ Passed |
| | |
| MOT #9 | 2017-02-24 10:25 |
| MOT test number | 941566752636 |
| Result | ✓ Passed |
| | |
| MOT #8 | 2016-03-11 12:37 |
| MOT test number | 509854541577 |
| Result | ✓ Passed |
| Advice Offside Front tyre has some cuts on inner wall | |
| Advice Nearside Front tyre has some cuts on outer wall | |

| MOT #7 | 2015-03-12 11:56 |
|-----------------|------------------|
| MOT test number | 396051675011 |
| Result | ✓ Passed |
| | |

| MOT #6 | 2014-03-17 15:55 |
|-----------------|------------------|
| MOT test number | 607256474078 |
| Result | ✓ Passed |





| MOT #5 | 2014-03-14 11:12 |
|---|------------------|
| MOT test number | 268413874018 |
| Result | 🗙 Failed |
| Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) | |
| MOT #4 | 2013-02-21 17:11 |
| MOT test number | 126962053413 |
| Result | ✓ Passed |
| Notice Under-trays fitted obscuring some underside components | |
| Notice Engine covers fitted obscuring some components in the engine bay | |
| MOT #3 | 2012-02-24 15:30 |
| MOT test number | 557935352086 |
| Result | ✓ Passed |
| MOT #2 | 2011-03-16 15:5 |
| MOT test number | 255255571089 |
| Result | ✓ Passed |
| MOT #1 | 2011-03-15 17:0 |
| MOT test number | 598774771092 |
| Result | 🗙 Failed |

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Notice O\s\f tyre light cracking

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

| Taxed Tax due: 1 August 2024 | MOT Expires: 22 August 2024 |
|---|-----------------------------------|
| Tax status | Valid until 1 August |
| Days left | 94 |
| MOT expiry date | 22 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | I |
| Single payment (12 months) | £ 320,00,- |
| Single six month payment | £ 176,00,- |
| Total payable by 12 monthly instalments | £ 336,00,- |





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|---------|
| Date | FEED ON |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPLE |
| Date | |
| Date | OLE I |
| Category | AM |
| Туре | |

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.700 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10 700 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ********** | |
|--|-------------|
| ********* | |
| | |
| | |
| ********** | |
| ACCOUNTS AND A DESCRIPTION OF A DESCRIPR | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this VOLKSWAGEN had different number plates. | |
| | |
| Number of plates | , |
| Rumber of plates Carrent registration | |
| Rumber of plates Carrent registration Plate since | |
| Rumber of plates Correct registration Fate since Correct registration | |
| Rumber of plates Current registration Plate since Current registration Plate since | 1000-20-20 |





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 19 |
| First mileage registration | 2008-03-01 |
| Last registration | 2023-08-23 |
| Complete history | See info |



| Registration #1 | 2008-03-01 | 18 mi |
|-------------------------|------------|------------|
| Registration #2 | 2011-03-15 | 17.205 mi |
| Registration #3 | 2011-03-16 | 17.221 mi |
| Registration #4 | 2012-02-24 | 23.204 mi |
| Registration #5 | 2013-02-21 | 29.451 mi |
| Registration #6 | 2014-03-14 | 35.973 mi |
| Registration #7 | 2014-03-17 | 36.074 mi |
| Registration #8 | 2015-03-12 | 39.148 mi |
| Registration #9 | 2016-03-11 | 42.167 mi |
| Registration #10 | 2017-02-24 | 45.207 mi |
| Registration #11 | | 11.777 esi |
| Registration #12 | | 11.777 est |
| Registration #13 | | 11.777 esi |
| Registration #14 | | 11.777 est |
| Registration #15 | | 11.777 esi |
| Registration #16 | | 11.777 est |
| Registration #17 | | 11.777 mi |
| | | |
| Registration #18 | | 11.777 est |

More info \rightarrow





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| 50482 | |
| \$0501 | |
| \$0566 | |
| \$0567 | |
| S0569 | |

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight Width 1791 mm Height 1437 mm Length 4407 mm Wheel base 2578 mm Max. allowed weight 2010 kg Additional information Eucl tank canacit - - I

| Fuel tank capacity | 55 |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 2 |
| Number of seats | 4 |
| CarCheck.co.uk | page 12/12 |

| Number of axles |
|-----------------|
| |

Engine number

BMM 212354

2