





General information

| Make | ΤΟΥΟΤΑ |
|---------------------|----------------|
| Model | PRIUS VVT-I T3 |
| Colour | Blue |
| Year of manufacture | - |
| Top speed | 106 mph |
| 0 - 60 mph | 10.9 seconds |
| Gearbox | 4 speed CVT |

Engine & fuel consumption

| Power | 76 BHP |
|-------------------------|---------------------|
| Max. torque | 115 Nm at 4.000 rpm |
| Cylinders | 4 |
| Fuel type | Electric |
| Consumption city | 56.5 mpg |
| Consumption extra urban | 67.3 mpg |
| Consumption combined | 65.7 mpg |



MOT history

| MOT #18 | | 2020-09-01 07:26 |
|-----------|---|---------------------|
| MOT test | number | 652560421108 |
| Result | | ✓ Passed |
| Next expi | ry date | 2021-09-06 |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a | a) (ii)) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Suspension component pin or bush slightly worn nsr and osr trailing arm bus | hes (5.3.4 (a) (i)) |

| MOT #17 | 2019-08-14 12:36 |
|---|------------------|
| MOT test number | 913907884353 |
| Result | 🗸 Passed |
| Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |) |

| MOT #16 | 2018-08-22 14:38 |
|-----------------|------------------|
| MOT test number | 892353077983 |
| Result | ✓ Passed |

| MOT #15 | | 2017-08-22 11:59 |
|----------|---|------------------|
| MOT test | number | 443891495506 |
| Result | | ✓ Passed |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) | |

| MOT #14 | 2016-08-16 13:26 |
|--|------------------|
| MOT test number | 126092783448 |
| Result | ✓ Passed |
| Advice Front Tyre worn close to the legal limit both (4.1.E.1) | |





| MOT #13 | 2015-09-07 14:22 |
|---|------------------|
| MOT test number | 912612033959 |
| Result | ✓ Passed |
| | |
| MOT #12 | 2014-07-25 09:42 |
| MOT test number | 567796804264 |
| Result | ✓ Passed |
| Notice Exhaust corroded | |
| Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2) | |

| MOT #11 | 2014-07-25 09:42 |
|---------------------------------|---|
| MOT test number | 215566704211 |
| Result | × Failed |
| Advice Rear Exhaust has a minor | leak of exhaust gases (7.1.2) |
| Notice Exhaust corroded | |
| Pass with rectification Offside | Front position lamp(s) not working (1.1.A.3b) |

| MOT #10 | | 2013-07-26 14:07 |
|----------|---|------------------|
| MOT test | number | 738127003216 |
| Result | | ✓ Passed |
| Advice | Offside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) | |



| DS06MEV |
|-------------------------|
| report date: 2024-03-29 |

| МОТ #9 | 2013-07-26 12:40 |
|--|------------------|
| MOT test number | 577997803245 |
| Result | 🗙 Failed |
| Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Fail Nearside Rear Tyre has ply or cords exposed (4.1.D.1b) | |

| MOT #8 | | 2012-07-26 16:32 |
|----------|--|------------------|
| MOT test | number | 429778702251 |
| Result | | ✓ Passed |
| Advice | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Offside Rear Tyre worn close to the legal limit (4.1.E.1) | |

| MOT #7 | 2012-07-25 11:35 |
|---|------------------|
| MOT test number | 868537702211 |
| Result | 🗙 Failed |
| Fail Offside Rear coil spring fractured (2.4.C.1a) Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1) Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1) | |

| MOT #6 | 2011-08-10 15:23 |
|--|------------------|
| MOT test number | 807062921265 |
| Result | 🗸 Passed |
| Advice Rear registration plate delaminated but not likely to be misread (6.3.1d) | |



DSO6MEV report date: 2024-03-29

| MOT #5 | 2011-08-10 09:59 |
|--|------------------|
| MOT test number | 529482821272 |
| Result | 🗙 Failed |
| Fail Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i) | |
| Advice Rear Brake pad(s) wearing thin (3.5.1g) | |
| Fail Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i) | |
| Advice Rear registration plate delaminated but not likely to be misread (6.3.1d) | |

| МОТ #4 | 2010-08-19 10:39 |
|--|------------------|
| MOT test number | 351271530434 |
| Result | ✓ Passed |
| Notice Near side rear tyre slightly wearing on outer edge | |

| MOT #3 | 2009-09-02 14:01 |
|-----------------|------------------|
| MOT test number | 351755749239 |
| Result | ✓ Passed |

| MOT #2 | 2009-06-17 13:40 |
|-----------------|------------------|
| MOT test number | 861378569162 |
| Result | ✓ Passed |

| MOT #1 | 2009-06-17 10:04 |
|--|------------------|
| MOT test number | 734028169181 |
| Result | 🗙 Failed |
| Advice Tyre worn close to the legal limit (4.1.E.1) | |
| Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) | |





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-------|
| Date | FET A |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPL |
| | |
| Date | Nº I |
| Category | ANNY. |
| Туре | |

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.700 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| xxxxxxxx | |
|---|-------------|
| ********** | |
| ******** | |
| ******* | |
| ********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this TOYOTA had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Carrent registration | |
| Plate since | |
| | More info > |





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 18 |
| First mileage registration | 2006-08-01 |
| Last registration | 2020-09-01 |
| Complete history | See info |



| Registration #1 | 2006-08-01 | 29 mi |
|------------------|------------|------------|
| Registration #2 | 2009-06-17 | 48.210 mi |
| Registration #3 | 2009-06-17 | 48.210 mi |
| Registration #4 | 2009-09-02 | 50.495 mi |
| Registration #5 | 2010-08-19 | 62.120 mi |
| Registration #6 | 2011-08-10 | 73.083 mi |
| Registration #7 | 2011-08-10 | 78.083 mi |
| Registration #8 | 2012-07-25 | 85.546 mi |
| Registration #9 | 2012-07-26 | 85.548 mi |
| Registration #10 | | 11.777 est |
| Registration #11 | | 11.777 esi |
| Registration #12 | | 11.777 esi |
| Registration #13 | | 11.777 esi |
| Registration #14 | | 11.777 est |
| Registration #15 | | 11.777 est |
| Registration #16 | | 11.777 est |
| Registration #17 | | 11.777 mi |
| Registration #18 | | 11.117 esi |





Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

NCAP rating

Video

see crash video



| Dimensions & weight | |
|-----------------------------------|-----------------------|
| Width | 1725 mm |
| Height | 1490 mm |
| Length | 4450 mm |
| Wheel base | 2700 mm |
| Kerb weight | 1325 kg |
| Max. allowed weight | 1725 kg |
| Additional information | |
| Fuel tank capacity | 45 |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

| Number of axles | 2 |
|-----------------|------------|
| Engine number | 1NZ4201111 |