



PEUGEOT




report date: 2024-03-28

General information

Make	PEUGEOT
Model	206 SPORT
Colour	Blue
Year of manufacture	2005
Top speed	111 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	87 BHP
Max. torque	133 Nm at 3.250 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	57.7 mpg
Consumption combined	46.3 mpg
CO2 emission	145 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-08-02
Pictures	11
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2024-05-10
MOT pass rate	63 %
MOT passed	15
Failed MOT tests	9
Total advice items	55
Total items failed	13

MOT #24	2023-05-11 12:36
MOT test number	253912557807
Result	✓ Passed
Next expiry date	2024-05-10
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #23	2023-05-11 10:52
MOT test number	305467731112
Result	✗ Failed
MAJOR	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
MAJOR	Rear fog lamp not working (4.5.1 (a) (ii))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #22	2022-03-14 12:07
MOT test number	304540793267
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #21**

2022-03-14 09:57

MOT test number

329191434857

Result**✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

MOT #20

2021-03-11 09:30

MOT test number

632661871789

Result**✓ Passed**

- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Central Exhaust has a minor leak of exhaust gases exhaust centre box corroded and detaching from pipe recommend replacement (6.1.2 (a))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #19**

2021-03-11 09:30

MOT test number

722800247330

Result

✗ Failed

Pass with rectification Rear fog lamp not working (4.5.1 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Central Exhaust has a minor leak of exhaust gases exhaust centre box corroded and detaching from pipe recommend replacement (6.1.2 (a))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #18**

2020-03-09 13:30

MOT test number

536119428966

Result

✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened front brake discs corroded slightly (1.1.14 (a) (ii))**Advice** Nearside nearside front windscreen washer jet not working**Advice** Fuel tank strap corroded**Advice** Nearside Rear Nail in tyre nearside rear tyre has nail inner shoulder**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Exhaust corroded slightly**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both front suspension lower arm bushes perishing (5.3.4 (a) (i))**MOT #17**

2019-03-13 12:35

MOT test number

248114639455

Result

✓ Passed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt



MOT #16	2018-02-09 12:49
MOT test number	371582784704
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit inner edge (4.1.E.1)

MOT #15	2018-02-09 11:51
MOT test number	600241366053
Result	✗ Failed
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm inner edge (4.1.E.1)
Fail	Offside Front Tyre tread depth below requirements of 1.6mm inner edge (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit inner edge (4.1.E.1)

MOT #14	2017-02-23 14:51
MOT test number	503321543178
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Rear exhaust corroded and mounting strap broken

**MOT #13**

2017-02-23 09:36

MOT test number

114546795963

Result**✗ Failed**

- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)
- Fail** Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Advice** Nearside front tyre worn on inner edge
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear exhaust corroded and mounting strap broken

MOT #12

2016-02-23 08:46

MOT test number

478638796206

Result**✓ Passed**

- Advice** Engine oil leak
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Rear exhaust corroded but not leaking

**MOT #11**

2016-02-23 08:46

MOT test number

329670570041

Result**✗ Failed**

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Engine oil leak

Pass with rectification Nearside Headlamp aim too low and too far to the right. (1.8)

Pass with rectification Nearside Registration plate lamp not working (1.1.C.1d)

Advice Rear exhaust corroded but not leaking

Pass with rectification Offside Headlamp aim too low (1.8)

MOT #10

2015-02-10 12:53

MOT test number

697131245059

Result**✓ Passed**

Notice Rear exhaust box outer skin corroded

Notice Drivers wiper blade split

Notice Oil leak

Notice Nearside rear tyre sidewall slightly perishing

Notice Exhaust flexi webbing starting to split

**MOT #9** 2015-02-10 12:53**MOT test number** 646261745041**Result** ✗ Failed**Notice** Exhaust flexi webbing starting to split**Notice** Rear exhaust box outer skin corroded**Pass with rectification** Windscreen has a sticker or other obstruction encroaching by more than 10mm within zone 'A' (8.3.1b)**Notice** Drivers wiper blade split**Notice** Oil leak**Notice** Nearside rear tyre sidewall slightly perishing**MOT #8** 2014-02-25 14:30**MOT test number** 916066654094**Result** ✓ Passed**MOT #7** 2014-02-25 14:30**MOT test number** 279866854025**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #6** 2013-07-17 09:22**MOT test number** 638498993173**Result** ✓ Passed**MOT #5** 2012-07-18 11:33**MOT test number** 326100402217**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #4	2011-06-23 08:34
MOT test number	258774271492
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #3	2010-01-21 12:27
MOT test number	174211920038
Result	✓ Passed

MOT #2	2008-09-27 11:45
MOT test number	154181078243
Result	✓ Passed

MOT #1	2008-09-27 09:19
MOT test number	551601078207
Result	✗ Failed
Fail	Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
10 May 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	10 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-09-21
Last registration	2023-05-11
Complete history	See info



Registration #1	2005-09-21	15 mi
Registration #2	2008-09-27	21.267 mi
Registration #3	2008-09-27	21.267 mi
Registration #4	2010-01-21	24.388 mi
Registration #5	2011-06-23	29.496 mi
Registration #6	2012-07-18	33.491 mi
Registration #7	2013-07-17	39.492 mi
Registration #8	2014-02-25	42.224 mi
Registration #9	2015-02-10	46.345 mi
Registration #10	2016-02-23	51.765 mi
Registration #11	2016-02-23	51.765 mi
Registration #12	2017-02-23	57.947 mi
Registration #13	2018-02-23	64.129 mi
Registration #14	2019-02-23	70.311 mi
Registration #15	2020-02-23	76.493 mi
Registration #16	2021-02-23	82.675 mi
Registration #17	2022-02-23	88.857 mi
Registration #18	2023-02-23	95.039 mi
Registration #19	2024-02-23	101.221 mi
Registration #20	2025-02-23	107.403 mi
Registration #21	2026-02-23	113.585 mi
Registration #22	2027-02-23	119.767 mi
Registration #23	2028-02-23	125.949 mi
Registration #24	2029-02-23	132.131 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1049 kg
Max. allowed weight	1515 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	FE010153160