



report date: 2024-03-29

General information

| | |
|---------------------|---------------------|
| Make | VAUXHALL |
| Model | CASCADA SE CDTI S/S |
| Colour | Black |
| Year of manufacture | 2015 |
| Top speed | 129 mph |
| 0 - 60 mph | 9.1 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 168 BHP |
| Max. torque | 400 Nm at 1.750 rpm |
| Engine capacity | 1.956 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 46.3 mpg |
| Consumption extra urban | 67.3 mpg |
| Consumption combined | 57.7 mpg |
| CO2 emission | 129 g/km |
| CO2 label | D |





Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2022-02-10 |
| Pictures | 21 |
| Listing price | View report |



source: [cargurus.co.uk](#)

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2022-02-09 |
| Pictures | 22 |
| Listing price | View report |



source: [autotrader.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-12-17 |
| MOT pass rate | 75 % |
| MOT passed | 6 |
| Failed MOT tests | 2 |
| Total advice items | 8 |
| Total items failed | 1 |

| | |
|------------------|--------------------------------------------------------------------------------------------|
| MOT #8 | 2023-12-14 13:01 |
| MOT test number | 259547108467 |
| Result | ✓ Passed |
| Next expiry date | 2024-12-17 |
| Advice | Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |

| | |
|-----------------|--------------------------------------------------------------------------------------------|
| MOT #7 | 2023-12-14 09:13 |
| MOT test number | 331146975258 |
| Result | ✗ Failed |
| Advice | Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| MAJOR | Offside Rear Inner Brake pad(s) worn down to wear indicator (1.1.13 (a) (i)) |

| | |
|-----------------|------------------|
| MOT #6 | 2022-11-22 10:51 |
| MOT test number | 817038942907 |
| Result | ✓ Passed |

**MOT #5** 2021-11-22 09:18**MOT test number** 403475168895**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge old 2015 y o m (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Engine bay covers obscuring testable components & prescribed areas**Advice** Brake pedal wearing smooth anti-slip rubber worn on edge (1.1.2 (c))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge old 2015 y o m (5.2.3 (e))**MOT #4** 2020-11-25 14:40**MOT test number** 421695367384**Result** ✓ Passed**MOT #3** 2019-11-19 09:17**MOT test number** 478250658209**Result** ✓ Passed**MOT #2** 2019-11-19 09:17**MOT test number** 346954770296**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**MOT #1** 2018-11-19 09:18**MOT test number** 988629592819**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
17 December 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 March |
| Days left | 305 |
| MOT expiry date | 17 December 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|------------------------------------------------|------------|
| Vehicle class | 49 |
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 15,200 |
| Auction value | £ 15,200 |
| Average private trade value | £ 15,200 |

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

| | |
|----------------------|-----------------------------------------------------------------------------------------------|
| Number of plates | 1 |
| Current registration |  DE55EZE |
| Plate since | 2019-03-29 |
| Current registration |  DE55EZE |
| Plate since | 2019-03-29 |

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 11 |
| First mileage registration | 2015-12-18 |
| Last registration | 2023-12-14 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2015-12-18 | 15 mi |
| Registration #2 | 2018-11-19 | 14,131 mi |
| Registration #3 | 2019-11-19 | 18,631 mi |
| Registration #4 | 2019-11-19 | 18,631 mi |
| Registration #5 | 2020-11-25 | 20,991 mi |
| Registration #6 | 2021-11-22 | 24,173 mi |
| Registration #7 | 2022-05-20 | 25,277 mi |
| Registration #8 | 2022-05-20 | 25,277 mi |
| Registration #9 | 2022-05-20 | 25,277 mi |
| Registration #10 | 2022-05-20 | 25,277 mi |
| Registration #11 | 2023-12-14 | 25,277 mi |

More info >



Safety ratings

| | |
|-------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2099 mm |
| Height | 1685 mm |
| Length | 4658 mm |
| Wheel base | 2760 mm |
| Kerb weight | 1658 kg |
| Max. allowed weight | 2455 kg |

Additional information

| | |
|--------------------|---------------------|
| Fuel tank capacity | 58 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 7 |
| Number of axles | 2 |
| Engine number | B20DTH -17E28148LFS |