



report date: 2024-03-28

General information

Make	VAUXHALL
Model	COMBO 2300 L2H1 CDTi
Colour	White
Year of manufacture	-
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	200 Nm at 1.500 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg




LABEL UNKNOWN



Internet history

Entry 2

Date	2022-02-10
Pictures	7
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-10-06
Pictures	0
Listing price	View report

source: cargurus.co.uk

**MOT history**

MOT #9	2023-01-31 10:39
MOT test number	725134046701
Result	✓ Passed
Next expiry date	2024-02-21
Advice	Items removed from driver's view prior to test
Advice	Offside Front Top mount worn

MOT #8	2023-01-25 16:02
MOT test number	359722103543
Result	✗ Failed
MAJOR	Nearside Headlamp light source and lamp not compatible LED bulb fitted resulting in no beam image and dazzling other road users (4.1.4 (c))
MAJOR	Nearside Side repeater light intensity significantly reduced (4.4.3 (a))
MAJOR	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
MAJOR	Offside Headlamp aim projected beam image is obviously incorrect LED bulb fitted (4.1.2 (c))
MAJOR	Offside Headlamp light source and lamp not compatible LED bulb fitted resulting in no beam image and dazzling other road users (4.1.4 (c))
MAJOR	Exhaust emissions exceed manufacturer's specified limit 0.52 (8.2.2.2 (a))
MAJOR	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
MAJOR	Nearside Headlamp aim projected beam image is obviously incorrect LED bulb fitted (4.1.2 (c))

MOT #7	2022-02-22 09:19
MOT test number	364067930428
Result	✓ Passed
Advice	Clutch pedal rubber missing
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #6**

2021-01-25 15:27

MOT test number

219533693504

Result

✓ Passed

Advice

Dsm will not register a reading

MOT #5

2021-01-22 12:38

MOT test number

786868925216

Result

✗ Failed

- MAJOR** Offside Headlamp aim not tested (4.1.2 (b))
- MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Offside Headlamp not working on main beam (4.1.1 (a) (ii))
- MAJOR** Nearside Headlamp aim too high (4.1.2 (a))
- MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Offside Headlamp insecure (4.1.1 (c))
- MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice

Dsm will not register a reading

MOT #4

2019-06-25 12:07

MOT test number

499803894156

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



MOT #3	2018-05-25 14:30
MOT test number	954896734829
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #2	2017-05-19 11:34
MOT test number	592486654887
Result	✓ Passed

MOT #1	2016-05-13 08:20
MOT test number	252184379593
Result	✓ Passed



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 LM13XHS
Plate since	2019-06-29
Current registration	 LM13XHS
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-05-31
Last registration	2023-01-31
Complete history	See info



Registration #1	2013-05-31	26 mi
Registration #2	2016-05-13	12,471 mi
Registration #3	2017-05-19	14,151 mi
Registration #4	2018-05-25	15,775 mi
Registration #5	2019-06-25	19,442 mi
Registration #6	2021-01-22	24,580 mi
Registration #7	2022-01-22	25,277 mi
Registration #8	2022-01-22	25,277 mi
Registration #9	2022-01-22	25,277 mi
Registration #10	2022-01-22	25,277 mi
Registration #11	2022-01-22	25,277 mi
Registration #12	2022-01-22	25,277 mi

More info >



Dimensions & weight

Width	2119 mm
Height	1880 mm
Length	4740 mm
Kerb weight	1330 kg
Max. allowed weight	2330 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	263A20004952810 LN9