





report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 LOOK
Colour	Black
Year of manufacture	2008
Top speed	106 mph
0 - 60 mph	14.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	120 Nm at 3.400 rpm
Engine capacity	1.360 сс
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.1 mpg
CO2 emission	152 g/km
CO2 label	G



CarCheck.co.uk page 1/15



Internet history

Entry 1

Date 2021-07-16

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



MOT history

MOT expiry date	2025-03-06
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	38
Total items failed	7

MOT #19		2024-03-02 13:28
MOT test	number	583193716302
Result		✓ Passed
Next expi	ry date	2025-03-06
Advice	Offside Front chassis is starting to corrode	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/15



MOT #18 2024-03-01 14:41

MOT test number 733581482902

Result X Failed

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MAJOR Front Exhaust has a major leak of exhaust gases (6.1.2 (a))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front chassis is starting to corrode

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MAJOR Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

DANGEROUS Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #17 2023-02-14 15:18

MOT test number 676065160894

Result

Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

CarCheck.co.uk page 4/15



FY08BVZ

✓ Passed

report date: 2024-03-29

MOT #16 2023-02-09 11:30

MOT test number 973270519663

Result X Failed

MAJOR Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MAJOR Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Advice Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

MOT #15 2022-02-11 11:47

MOT test number 608799855665

Advice Nearside Front SHOCKER TOP MOUNT CORRODED

Advice ENGINE OIL LEAK

Result

Advice Nearside Front ANTI ROLL BAR LINK

MOT #14 2021-03-03 17:28

MOT test number 649439301490

Advice Offside Front Lower Oil leak, but not excessive (8.4.1 (a) (i))

MOT #13 2020-02-28 17:02

MOT test number 674746580557

Result
✓ Passed

CarCheck.co.uk page 5/15



MOT #12 2019-02-18 15:02

MOT test number 851860605544

Result ✓ Passed

Minor

Nearside Lower Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #11 2018-02-21 10:52

MOT test number 683515792101

Result
✓ Passed

Advice Nearside Front Lower Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

MOT #10 2017-02-28 16:26

MOT test number 740481914079

Result \(\sqrt{Passed} \)

MOT #9 2017-02-28 09:44

MOT test number 353369013942

Result X Failed

Fail Nearside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Offside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #8 2016-03-03 09:57

MOT test number 572975947634

Result ✓ Passed

Advice Tyre worn close to the legal limit both front (4.1.E.1)

Advice Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 6/15



FY08BVZ

report date: 2024-03-29

× Failed

MOT #7 2016-03-02 09:16

MOT test number 113464413409

Result X Failed

Advice Front Brake pad(s) wearing thin (3.5.1g)

Fail Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice Tyre worn close to the legal limit both front (4.1.E.1)

Fail Exhaust system not adequately supported (7.1.1)

Fail Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #6 2015-02-13 09:08

MOT test number 268774045014

Result \rightarrow Passed

MOT #5 2014-02-18 12:54

MOT test number 298209544016

Result ✓ Passed

MOT #4 2013-03-06 12:11

MOT test number 799495863015

Result

Passed

MOT #3 2013-03-06 12:11

MOT test number 448765163037

Pass with rectification Front Headlamp aim too low (1.8)

Result

CarCheck.co.uk page 7/15



MOT test number

Result

Advice

Nearside Headlamp damaged but light output not reduced (1.7.5a)

Notice

Rear exhaust slightly deteriorated

Advice

Front Brake pad(s) wearing thin (3.5.1g)

Advice

Offside Headlamp deteriorated but light output not reduced (1.7.5a)

MOT #1		2011-03-07 09:48
MOT test	number	117406061453
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 8/15



Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	6 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 9/15



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



Owner history

•		
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		GEOT

	More info	>
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		9
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 12/15



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 13/15



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-03-04
Last registration	2024-03-02
Complete history	See info



Registration #1	2008-03-04	9 mi
Registration #2	2011-03-07	18.619 mi
Registration #3	2012-03-05	28.182 mi
Registration #4	2013-03-06	37.824 mi
Registration #5	2014-02-18	40.527 mi
Registration #6	2015-02-13	42.958 mi
Registration #7	2016-03-02	45.498 mi
Registration #8	2016-03-03	45.498 mi
Registration #9	2017-02-28	48.870 mi
Registration #10	2017-02-28	48.871 mi
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		9.70 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		71.777 es

More info >

CarCheck.co.uk page 14/15



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1025 kg
Max. allowed weight	1450 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 15/15

Number of axles 2

Engine number FST65823851