





report date: 2024-03-29

#### General information

Make	HONDA
Model	CR-V I-DTEC SE NAVI
Colour	Grey
Year of manufacture	2016
Top speed	125 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	158 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	1.597 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	60.1 mpg
Consumption combined	57.7 mpg
CO2 emission	129 g/km
CO2 label	D



CarCheck.co.uk page 1/11



## Internet history

#### Entry 1

Date	2021-01-31	
Pictures	1	
Listing price	View report	



source: autoonline.co.uk

CarCheck.co.uk page 2/11



2024-04-09 09:35

MOT history

MOT #7

MOT expiry date	2025-04-15
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	7
Total items failed	2

MOT #8	2024-04-09 13:22
MOT test number	986046138368
Result	✓ Passed
Next expiry date	2025-04-15

MOT test number	148074424143
Result	<b>X</b> Failed
Fail Nearside Rear Tyre has a tear, caused by separation or partial failure of its	structure and cords
exposed (5.2.3 (d) (ii))	

MOT #6	2023-04-05 08:54
MOT test number	621692825881
Result	✓ Passed

MOT #5	2022-04-13 09:36
MOT test number	316024104254
Result	✓ Passed

MOT #4		2021-04-16 12:06
MOT test	number	957381489310
Result		✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii	))

CarCheck.co.uk page 3/11



MOT #3 2021-04-09 10:44

MOT test number 608323287313

**Result** X Failed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Front Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))

MOT #2 2020-10-14 15:56

**MOT test number** 528822459177

Result Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both. (1.1.14 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #1** 2019-09-26 14:04

**MOT test number** 815283474879

CarCheck.co.uk page 4/11



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	15 April 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.		Α
********		
***************************************		
***************************************		
***************************************		
	More info	>
Plate changes  See in this check if this HONDA had different number plates.		
Number of plates		,
Current registration	UK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-09-26
Last registration	2024-04-09
Complete history	See info



Registration #1	2016-09-26	13 mi
Registration #2	2019-09-26	38.495 mi
Registration #3	2020-10-14	44.718 mi
Registration #4		11.777 es
Registration #5	2021-04-09	44.746 mi
Registration #6		77,777 44
Registration #6 Registration #7		11.777 es
		11.777 es
Registration #7		11,777 es 11,777 es 11,777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

# Safety ratings

NCAP rating	****
Adult	93%
Children	74%
Pedestrian	68%
Safety systems	66%
Overall rating	81%
Video	see crash video



# Dimensions & weight

Width	1820 mm
Height	1685 mm
Length	4605 mm
Wheel base	2630 mm
Kerb weight	1718 kg
Max. allowed weight	2170 kg

## Additional information

Fuel tank capacity	58 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	N16A41019956

CarCheck.co.uk page 11/11