



Mercedes-Benz

 **BSZ7692**


report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	CLS CLS220 BLUETEC AMG LINE
Colour	Blue
Year of manufacture	2015
Top speed	138 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	174 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	129 g/km
CO2 label	D






Internet history

Entry 2


Date	2022-12-19
Pictures	4
Listing price	View report



source: autotrader.co.uk

Entry 1

Date	2022-02-21
Pictures	41
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-19
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	25
Total items failed	7

MOT #10 2024-02-06 15:07

MOT test number 486069195008

Result ✓ Passed

Next expiry date 2025-02-19

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9 2023-02-20 15:41

MOT test number 973153379926

Result ✓ Passed

- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #8 2023-02-15 17:23

MOT test number 497253838496

Result ✗ Failed

- Fail** Service brake efficiency below requirements (1.2.2 (a) (i))
- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Fail** Front Brakes imbalanced across an axle Axle 1 (1.2.1 (b) (i))



MOT #7	2022-02-03 17:49
MOT test number	791876908005
Result	✓ Passed

MOT #6	2021-03-06 09:59
MOT test number	640818764501
Result	✓ Passed
Advice	Nearside Front level rod ball joints seized
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material corroded slightly (1.1.11 (c))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5	2021-03-06 08:45
MOT test number	475521758837
Result	✗ Failed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material corroded slightly (1.1.11 (c))
Advice	Nearside Front level rod ball joints seized
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))



MOT #4 2020-02-15 12:37

MOT test number 293171805066

Result ✓ Passed

- Advice** Engine covers fitted, unable to fully inspect.
- Minor** Offside Front Windscreen wiper blade defective Smearing on screen. (3.4 (b) (i))
- Minor** Nearside Front Windscreen wiper blade defective Smearing on screen. (3.4 (b) (i))
- Advice** Under trays fitted, unable to fully inspect.

MOT #3 2020-02-15 10:52

MOT test number 245109550250

Result ✗ Failed

- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm 1.2mm (5.2.3 (e))
- Advice** Engine covers fitted, unable to fully inspect.
- Minor** Offside Front Windscreen wiper blade defective Smearing on screen. (3.4 (b) (i))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm 1.0mm (5.2.3 (e))
- Minor** Nearside Front Windscreen wiper blade defective Smearing on screen. (3.4 (b) (i))
- Advice** Under trays fitted, unable to fully inspect.

MOT #2 2019-03-02 12:06

MOT test number 515018024325

Result ✓ Passed

- Advice** Engine covers fitted, unable to fully inspect.
- Advice** Under trays fitted, unable to fully inspect.



MOT #1 2019-03-02 09:43

MOT test number 931149540329

Result ✗ Failed

Advice Under trays fitted, unable to fully inspect.

Fail Engine MIL inoperative or indicates a malfunction Engine Management light illuminated. (8.2.2.2 (g))

Advice Engine covers fitted, unable to fully inspect.



Tax & MOT check

✓
Taxed

Tax due:
1 March 2025

✓
MOT

Expires:
19 February 2025

Tax status Valid until 1 March

Days left 306

MOT expiry date 19 February 2025

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-




Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	XXXXX
Plate since	2023-03-28
Current registration	XXXXX
Plate since	2023-03-28

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-04-10
Last registration	2024-02-06
Complete history	See info



Registration #1	2015-04-10	12 mi
Registration #2	2019-03-02	46.115 mi
Registration #3	2019-03-02	46.115 mi
Registration #4	2020-02-15	75.864 mi
Registration #5	2020-02-15	75.864 mi
Registration #6	2021-03-06	93.607 mi
Registration #7	2021-03-06	93.607 mi
Registration #8	2022-03-06	93.607 mi
Registration #9	2022-03-06	93.607 mi
Registration #10	2022-03-06	93.607 mi
Registration #11	2022-03-06	93.607 mi
Registration #12	2022-03-06	93.607 mi
Registration #13	2024-02-06	93.607 mi

[More info >](#)



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	81%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2075 mm
Height	1418 mm
Length	4937 mm
Wheel base	2874 mm
Kerb weight	1790 kg
Max. allowed weight	2275 kg

Additional information

Fuel tank capacity	59 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	4
Number of axles	2
Engine number	65192432556533