



report date: 2024-03-29

General information

Make	SUZUKI
Model	ALTO SZ4
Colour	Green
Year of manufacture	2009
Top speed	96 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-05-24
Pictures	43
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-30
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	20
Total items failed	8

MOT #15	2024-01-11 14:38
MOT test number	376134709770
Result	✓ Passed
Next expiry date	2025-01-30
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

MOT #14	2023-01-31 14:17
MOT test number	263818643155
Result	✓ Passed
Advice	Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #13**

2023-01-18 16:07

MOT test number

916138729680

Result

✗ Failed

Advice Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))**Fail** Offside Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Fail** Rear Brake pipe excessively corroded both (1.1.11 (c))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #12**

2022-01-14 11:28

MOT test number

164961253049

Result

✓ Passed

Advice Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))**Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11**

2021-01-09 09:12

MOT test number

115446658356

Result

✓ Passed

Advice Items removed from driver's view prior to test**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**MOT #10**

2019-06-26 16:02

MOT test number

575044664542

Result

✓ Passed

Advice Items removed from driver's view prior to test**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))

**MOT #9** 2018-07-07 10:03**MOT test number** 563517875654**Result** ✓ Passed**MOT #8** 2018-07-07 10:03**MOT test number** 565613326977**Result** ✗ Failed**Pass with rectification** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Pass with rectification** Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #7** 2017-06-27 10:15**MOT test number** 572871883650**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**MOT #6** 2017-06-27 10:15**MOT test number** 452499669824**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Items removed from driver's view prior to test**Pass with rectification** Nearside Headlamp aim too low and too far to the left. (1.8)**MOT #5** 2016-07-07 14:34**MOT test number** 588516184220**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #4** 2015-07-20 16:54**MOT test number** 269441305257**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Nearside rear tyre cracking/perishing**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Offside rear tyre cracking/perishing**MOT #3** 2014-07-25 12:04**MOT test number** 269926004204**Result** ✓ Passed**MOT #2** 2013-08-14 10:59**MOT test number** 125656323250**Result** ✓ Passed**MOT #1** 2012-09-11 11:18**MOT test number** 345665552445**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
30 January 2025

Tax status	Valid until 1 August
Days left	94
MOT expiry date	30 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-09-09
Last registration	2024-01-11
Complete history	See info



Registration #1	2009-09-09	26 mi
Registration #2	2012-09-11	9.002 mi
Registration #3	2013-08-14	10.548 mi
Registration #4	2014-07-25	12.909 mi
Registration #5	2015-07-20	16.985 mi
Registration #6	2016-07-07	20.771 mi
Registration #7	2017-06-27	24.505 mi
Registration #8	2017-06-27	24.505 mi
Registration #9	2018-07-07	32.552 mi
Registration #10	2019-06-27	35.277 mi
Registration #11	2020-06-27	38.002 mi
Registration #12	2021-06-27	40.727 mi
Registration #13	2022-06-27	43.452 mi
Registration #14	2023-06-27	46.177 mi
Registration #15	2024-01-11	48.902 mi
Registration #16	2024-01-11	48.902 mi
Registration #17	2024-01-11	48.902 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	see crash video



Dimensions & weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	K10BN 1009612