





### General information

Make	ΤΟΥΟΤΑ
Model	VERSO D-4D ICON
Colour	Black
Year of manufacture	2015
Top speed	112 mph
0 - 60 mph	12.7 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 2.400 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С








# Internet history

Entry 1	
Date	2021-12-06
Pictures	19
Listing price	View report









source: cargurus.co.uk



### MOT history

MOT expiry date	2025-01-08
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	21
Total items failed	2

MOT #8	2024-01-09 10:20
MOT test number	516296787089
Result	✓ Passed
Next expiry date	2025-01-08
Minor Offside Front Tyre obviously under inflated (5.2.3 (I))	

MOT #7	2022-12-21 10:58
MOT test number	446529738161
Result	✓ Passed
Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Offside Front Tyre obviously under inflated (5.2.3 (l))	

MOT #6	2021-12-30 13:05
MOT test number	757047620413
Result	✓ Passed





MOT #5		2021-03-26 12:10
MOT test	number	159711744582
Result		✓ Passed
Advice	Child Seat fitted not allowing full inspection of adult belt	
Advice	TPMS light on	
Advice	Play in steering rack inner joint(s)	
MOT #4		2020-04-01 14:45
MOT test	number	249647956897
Result		✓ Passed
Advice	Front Tyres worn low on edges, 3mm.	
Advice	Offside Rear Tyre wearing low, has crack.	
Advice	Rear Wiper split.	
Advice	Front Chip in windscreen.	

Advice Nearside Rear Tyre wearing low, has crack/ 3mm.

Advice Nearside Front Fog light not working.



W	Ν	1	5	C	)F	W
	rep	ort	dat	:e:	2024	-03-29

MOT #3	2020-04-01 14:45
MOT test number	881530506712
Result	🗙 Failed
Advice Rear Wiper split.	
Advice Front Chip in windscreen.	
Pass with rectification Front Windscreen wiper does not clear the windscreen	effectively (3.4 (b) (ii))
Advice Nearside Rear Tyre wearing low, has crack/ 3mm.	
Advice Nearside Front Fog light not working.	
Pass with rectificationTyre pressure monitoring system malfunctioning or obv(h))	viously inoperative (5.2.3
Advice Front Tyres worn low on edges, 3mm.	
Advice Offside Rear Tyre wearing low, has crack.	

MOT #2		2019-03-29 15:12
MOT test	number	364511954626
Result		✓ Passed
Advice	Offside wiper smears	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge also rear tyres p	erished (5.2.3 (e))
Advice	Child Seat fitted not allowing full inspection of adult belt OSR and NSR no a	ccess to rear belts

MOT #1	2018-03-29 16:31
MOT test number	989770196440
Result	✓ Passed



report date: 2024-03-29

## Tax & MOT check

✓ Taxed Tax due: 1 December 2024	✓ MOT Expires: 8 January 2025
Tax status	Valid until 1 December
Days left	215
MOT expiry date	8 January 2025
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	AMPLI
Damage 2	E E H - S - A
Date	*
Category	AMP.
Туре	

#### Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10.200





### Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

******	
***********	
*******	
******	
***********	
********	
	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-03-26
Last registration	2024-01-09
Complete history	See info



Registration #1	2015-03-26	16 mi
Registration #2	2018-03-29	43.137 mi
Registration #3	2019-03-29	54.135 mi
Registration #4	2020-04-01	64.586 mi
Registration #5	2020-04-01	64.586 mi
Registration #6		11.177 esi
Registration #7		11.177 esi
Registration #8		11.177 esi
Registration #9		11.777 esi
Registration #10		





## Car features

S0225	Air conditioning
\$0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	89%
Children	75%
Pedestrian	69%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight	
Width	1790 mm
Height	1630 mm
Length	4460 mm
Wheel base	2780 mm
Kerb weight	1620 kg
Max. allowed weight	2260 kg
Additional information	
Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/12

Number of axles	2
Engine number	N470649294