





report date: 2024-03-28

General information

Make	MINI
Model	COUNTRYMAN COOPER D ONE D
Colour	White
Year of manufacture	2011
Top speed	106 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/11



PK61RV0
report date: 2024-03-28

Internet history

E ~	+	. 1
	ILIV	

Life y 1	
Date	2021-12-01
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/11



PK61RV0
report date: 2024-03-28

MOT history

MOT expiry date	2025-04-10
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	10
Total items failed	3

MOT #12	2024-03-19 15:51
MOT test number	514270795248
Result	✓ Passed
Next expiry date	2025-04-10
Minor Nearside Upper Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #11		2023-04-11 09:16
MOT test	number	319353831280
Result		✓ Passed
Advice	Offside Rear Valve stem slightly damaged Perished (5.2.3 (j))	
Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))		
Advice	Rear Registration plate deteriorated but not likely to be misread Damaged (0.1 (b))

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #10 2023-04-03 08:50 327380058860 **MOT** test number Result × Failed Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) **Advice** Rear Registration plate deteriorated but not likely to be misread Damaged (0.1 (b)) **Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f)) Advice Offside Rear Valve stem slightly damaged Perished (5.2.3 (j)) Central Rear Stop lamp(s) not working High level (4.3.1 (a) (ii)) Fail

MOT #9

MOT test number

Result

Advice Nearside Rear Tyre slightly damaged/cracking or perishing Tread also low (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #8
 2021-03-30 15:10

 MOT test number
 538321308456

 Result
 ✓ Passed

 MOT #7
 2020-02-21 14:19

 MOT test number
 426678667549

 Result
 ✓ Passed

MOT #6

MOT test number

Result

Fail Offside Rear Road wheel fixing missing (5.2.1 (a) (i))

CarCheck.co.uk page 4/11



PK61RV0
report date: 2024-03-28

MOT #5

MOT test number

Second Seco

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
MOT #4	2018-01-24 10:35	
MOT test number	213603801462	
Result	✓ Passed	
MOT #3	2016-11-22 15:54	
MOT test number	249617689682	
Result	✓ Passed	
MOT #2	2015-11-24 09:48	
MOT test number	189048308964	
Result	✓ Passed	
MOT #1	2014-11-11 12:33	
MOT test number	657145514372	
Result	✓ Passed	

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

\sim		h:at	
-C)V	vner	misi	or

For how long did the current and previous owner(s) have this MINI? How many owners did Check it in the premium report and see all owner registrations. Download the full report is		e?
manage of the same		

	More info	>
Plate changes		
See in this check if this MINI had different number plates.		
Number of plates		9
Current registration	NK NE	
Plate since		
Current registration	OK NE	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-11-24
Last registration	2024-03-19
Complete history	See info



Registration #1	2011-11-24	15 mi
Registration #2	2014-11-11	34.873 mi
Registration #3	2015-11-24	56.950 mi
Registration #4	2016-11-22	77.559 mi
Registration #5	2018-01-24	79.988 mi
Registration #6	2019-02-14	85.921 mi
Registration #7	2020-02-21	92.914 mi
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
60482	
60501	
0566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	47
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 11/11

Engine number

73317833