



RENAULT




report date: 2024-03-29

General information

Make	RENAULT
Model	GRAND SCENIC GRAND DYNAMIQUE TOMTOM VVT
Colour	Grey
Year of manufacture	2011
Top speed	115 mph
0 - 100 km/h	12.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	162 kW / 221 HP / 110 BHP
Max. torque	151 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.2 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg
CO2 emission	178 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-10-13
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-01
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	41
Total items failed	13

MOT #16	2023-10-28 12:01
MOT test number	431108762569
Result	✓ Passed
Next expiry date	2024-11-01
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #15	2022-11-02 13:53
MOT test number	217638748213
Result	✓ Passed

MOT #14	2022-10-27 12:05
MOT test number	634661249966
Result	✗ Failed
Fail	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #13**

2021-10-25 15:33

MOT test number

421850375609

Result

✓ Passed

Advice Front Suspension component mounting prescribed area is corroded but not considered excessive Both sides (5.3.6 (a) (i))

MOT #12

2020-10-28 16:13

MOT test number

605705683240

Result

✓ Passed

Advice Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Front Play in steering rack inner joint(s)

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside sill damaged

**MOT #11**

2020-10-28 08:57

MOT test number

144246271843

Result**✗ Failed****Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Rear Service brake lagging in operation (1.2.1 (d))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened or showing signs of over heating (1.1.14 (a) (ii))**Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**Advice** Nearside sill damaged**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #10**

2019-03-26 13:33

MOT test number

610274166054

Result

✓ Passed

- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge bandd worn out of shape . (5.2.3 (e))
- Advice** Brake pipe corroded, covered in grease or other material Front to rear at offside rear . (1.1.11 (c))
- Advice** Play in steering rack inner joint(s) Offside & nearside .
- Advice** Offside Front Outer Cv boot deteriorated .
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge band worn out of shape . (5.2.3 (e))
- Advice** Offside Front tyre inner & outer bands worn out of shape .

MOT #9

2019-03-26 09:49

MOT test number

737335946966

Result

✗ Failed

- Fail** Nearside Rear Outer Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Brake pipe corroded, covered in grease or other material Front to rear at offside rear . (1.1.11 (c))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Front Outer Cv boot deteriorated .
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge band worn out of shape . (5.2.3 (e))
- Fail** Central Rear Seat belt not functioning as intended (7.1.2 (c))
- Advice** Play in steering rack inner joint(s) Offside & nearside .
- Advice** Offside Front tyre inner & outer bands worn out of shape .
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge bandd worn out of shape . (5.2.3 (e))

**MOT #8** 2018-03-29 10:23**MOT test number** 744535188900**Result** ✓ Passed**MOT #7** 2018-03-29 08:48**MOT test number** 180247932507**Result** ✗ Failed**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Central Rear Statutory seat belt missing (5.1.1)**MOT #6** 2017-03-20 17:27**MOT test number** 954846342157**Result** ✓ Passed**MOT #5** 2017-03-20 12:11**MOT test number** 333902291729**Result** ✗ Failed**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Rear Outer Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #4** 2016-03-29 10:23**MOT test number** 752498635478**Result** ✓ Passed**MOT #3** 2015-03-28 15:02**MOT test number** 578417385028**Result** ✓ Passed



MOT #2	2015-03-21 13:41
MOT test number	538480485030
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #1	2014-03-31 10:17
MOT test number	949240694058
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
1 November 2024

Tax status	Valid until 1 March
Days left	306
MOT expiry date	1 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	SK11MXW
Plate since	2019-03-29
Current registration	SK11MXW
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.


Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	0123 456789

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-03-31
Last registration	2023-10-28
Complete history	See info



Registration #1	2011-03-31	28 mi
Registration #2	2014-03-31	39.718 mi
Registration #3	2015-03-21	47.488 mi
Registration #4	2015-03-28	47.640 mi
Registration #5	2016-03-29	57.493 mi
Registration #6	2017-03-20	67.499 mi
Registration #7	2017-03-20	67.499 mi
Registration #8	2018-03-29	80.167 mi
Registration #9	2018-03-29	80.169 mi
Registration #10	2019-03-29	90.167 mi
Registration #11	2019-03-29	90.167 mi
Registration #12	2019-03-29	90.167 mi
Registration #13	2019-03-29	90.167 mi
Registration #14	2019-03-29	90.167 mi
Registration #15	2019-03-29	90.167 mi
Registration #16	2019-03-29	90.167 mi
Registration #17	2019-03-29	90.167 mi
Registration #18	2019-03-29	90.167 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	76%
Pedestrian	42%
Safety systems	99%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1478 mm
Height	1645 mm
Length	4560 mm
Wheel base	2770 mm
Kerb weight	1444 kg
Max. allowed weight	2074 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	D087530