





report date: 2024-03-28

General information

Make	HONDA
Model	CR-Z I-VTEC IMA GT
Colour	Black
Year of manufacture	2010
Top speed	124 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	235 Nm at 4.800 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	46.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	117 g/km
CO2 label	C



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

г.			- 1	
-1	nт	rv	, ,	

Elitiy 1	
Date	2022-01-16
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2024-11-28
MOT pass rate	100 %
MOT passed	11
Failed MOT tests	0
Total advice items	11
Total items failed	0

MOT #11	2023-11-28 13:01
MOT test number	271261771169
Result	✓ Passed
Next expiry date	2024-11-28

MOT #10	2022-11-25 15:38
MOT test number	980176069277
Result	✓ Passed

MOT #9	2021-11-29 09:00
MOT test number	420944487637
Result	✓ Passed
Advice All four brake discs corroded	

MOT #8	2020-09-07 09:41
MOT test number	361488663913
Result	✓ Passed

MOT #7	2019-09-04 12:05
MOT test number	381519943597
Result	✓ Passed
Advice Rear brake discs corroded	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #6	2018-08-23 13:41

MOT test number 294141729061

MOT #5 2017-08-14 15:52

MOT test number 861775638375

Result ✓ Passed

MOT #4 2016-08-15 10:42

MOT test number 223590202801

Result \(\sqrt{Passed} \)

MOT #3 2015-08-19 10:20

MOT test number 706228967555

Result ✓ Passed

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened inner edge (3.5.1i)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2 2014-08-28 10:59

MOT test number 678450644277

Result \(\sqrt{Passed} \)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT test number

429476943242

Result

Notice Child seat fitted not allowing full inspection of adult belt

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	28 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	С
Single payment (12 months)	£ 25,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 26,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

More info >

Owner history	
For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full	
HARMAN CO.	

HARMAN CO.	

	More info >
Plate changes	
See in this check if this HONDA had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	NK NK
Plate since	

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2010-09-10
Last registration	2023-11-28
Complete history	See info



Registration #1	2010-09-10	22 mi
Registration #2	2013-09-03	15.777 mi
Registration #3	2014-08-28	18.187 mi
Registration #4	2015-08-19	20.237 mi
Registration #5	2016-08-15	22.533 mi
Registration #6	2017-08-14	24.205 mi
Registration #7	2018-08-23	26.642 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.777 mi
Registration #12		0.00 44
Registration #13		10.777 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	93%
Children	80%
Pedestrian	71%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2014 mm
Height	1395 mm
Length	4080 mm
Wheel base	2425 mm
Kerb weight	1198 kg
Max. allowed weight	1520 kg

Additional information

Fuel tank capacity	40 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	LEA1 1009554

CarCheck.co.uk page 12/12