





report date: 2024-03-28

General information

Make	MERCEDES
Model	SPRINTER 311 CDI LWB P/V
Colour	Black
Year of manufacture	2009
Gearbox	6 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	280 Nm at 1.600 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/12



PK59LOF report date: 2024-03-28

MOT history

MOT expiry date	2024-12-13
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	24
Total items failed	3

MOT #15	2023-12-14 10:51
MOT test number	389409158296
Result	✓ Passed
Next expiry date	2024-12-13
Advice Rear Anti-roll bar pin or bush worn but not resulting in excessive movement B (5.3.4 (a) (i))	oth rear "D" bush
Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	

MOT #14		2023-12-14 10:51
MOT test number		573613788497
Result		X Failed
Advice Offside Front Tra	ck rod end ball joint has slight play (2.1.3 (b) (i))	
Pass with rectification	Offside Front Headlamp aim too high (4.1.2 (a))	
Advice Rear Anti-roll ba (5.3.4 (a) (i))	pin or bush worn but not resulting in excessive moveme	ent Both rear "D" bush
Pass with rectification	Nearside Front Headlamp aim too low (4.1.2 (a))	
Pass with rectification	Supplementary restraint system warning lamp indicates	s a fault (7.1.6 (a))

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT #13 2023-03-01 10:03

MOT test number 882025915833

Result ✓ Passed

Advice Offside Front Inner Play in steering rack inner joint(s)

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Minor Front Windscreen wiper blade defective BOTH (3.4 (b) (i))

MOT #12 2022-03-25 16:01

MOT test number 197118594384

Result
✓ Passed

MOT #11 2022-03-25 10:47

MOT test number 216119102966

Result × Failed

MAJOR Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

DANGEROUS Stop lamp(s) all not working (4.3.1 (a) (iii))

MAJOR Parking brake lever defective so that it cannot be satisfactorily operated Lever insecure (pivot bolt loose) (1.1.6 (d))

MOT #10 2021-06-10 09:05

MOT test number 762145991804

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #9 2021-06-09 11:30 **MOT** test number 683123409734 Result × Failed **MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a)) **MAJOR** Offside Outline marker lamp not working all offside side marker lamps inop (4.2.1 (a) (ii)) Hazard warning switch faulty works for approx. 1 min then goes off (4.4.2 (a) (i)) Minor Nearside Outline marker lamp not working all nearside side marker lamps inop (4.2.1 (a) (ii)) **MAJOR** Offside Rear fog lamp not working (4.5.1 (a) (ii)) MAJOR

MOT #8

MOT test number

Result

Advice Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Offside Front shock absorber piston worn

MOT test number

675698928349

Result

Advice Offside Front shock absorber piston worn

MAJOR Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Offside Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #6

MOT test number

Result

Advice Slight play in both front shock absorber inserts

2019-03-09 11:01

145882183910

✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT test number 773909582084

Result ✓ Passed

MOT #4 2017-03-14 13:56

MOT test number 538502612806

✓ Passed Result

MOT #3 2016-03-08 13:18

665033067145 **MOT test number**

Result ✓ Passed

Advice

Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)

MOT #2 2015-06-29 10:44

516350985109 **MOT test number**

Result ✓ Passed

MOT #1 2012-10-03 17:30

206407972234 **MOT test number**

Result ✓ Passed

Notice Os door check stapp pulled out ot piller

CarCheck.co.uk page 5/12



report date: 2024-03-28





Days left 34

MOT expiry date 13 December 2024

Full MOT history See MOT history

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



PK59LOF report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

More info >

Owner history

*		
For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downloaner.		

	More info >	
Plate changes		
See in this check if this MERCEDES had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK LINE	
Plate since		

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-10-07
Last registration	2023-12-14
Complete history	See info



Registration #1	2009-10-07	14 mi
Registration #2	2012-10-03	71.499 mi
Registration #3	2015-06-29	79.859 mi
Registration #4	2016-03-08	79.915 mi
Registration #5	2017-03-14	84.964 mi
Registration #6	2018-03-02	89.343 mi
Registration #7	2019-03-09	92.171 mi
Registration #8	2020-05-21	93.413 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.177 es
Registration #13		11.777 mi
Registration #14		0.00 44
Registration #15		11.777 mg

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 11/12



PK59LOF report date: 2024-03-28

Safety ratings

NCAP rating

Video <u>see crash video</u>



Dimensions & weight

Width	1960 mm
Height	3050 mm
Length	6940 mm
Kerb weight	2280 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	75 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Number of axles	2
Engine number	64698551773317

CarCheck.co.uk page 12/12