



General information

Make	MINI
Model	ONE AUTO COOPER
Colour	Silver
Year of manufacture	2013
Top speed	122 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	122 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	150 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-07-18
Pictures	18
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-08
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	20
Total items failed	8

MOT #11	2023-12-09 10:57
MOT test number	141874252417
Result	✓ Passed
Next expiry date	2024-12-08

MOT #10	2022-09-17 07:38
MOT test number	926341481695
Result	✓ Passed

MOT #9	2021-07-27 07:25
MOT test number	927494574656
Result	✓ Passed

**MOT #8**

2020-07-31 16:12

MOT test number

356646861331

Result

✓ Passed

- Advice** Nearside Rear Nail in tyre
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Exhaust emits blue smoke during acceleration (8.2.1.2 (g))
- Advice** TPMS lamp on
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Nearside Rear Tyre obviously under inflated (5.2.3 (l))

MOT #7

2019-07-08 07:31

MOT test number

161657764733

Result

✓ Passed

MOT #6

2019-07-06 11:33

MOT test number

204429755512

Result

✗ Failed

- Fail** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
- Fail** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #5**

2018-07-04 14:29

MOT test number

983082157902

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #4

2018-07-03 12:19

MOT test number

132238294516

Result

✗ Failed

- Fail** Offside Windscreen washer not working (3.5 (a))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Windscreen washer not working (3.5 (a))
- Fail** Brake pad(s) wear indicator illuminated (1.1.13 (a) (i))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened all 4 (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3

2017-07-04 15:44

MOT test number

918963328285

Result

✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Nail in tyre



MOT #2	2017-07-04 12:59
MOT test number	521750804822
Result	✗ Failed
Fail	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
Advice	Nearside Rear Nail in tyre
Advice	Rear Brake pad(s) wearing thin (3.5.1g)

MOT #1	2016-04-19 09:35
MOT test number	906943911341
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 January 2025

✓
MOT

Expires:
8 December 2024

Tax status	Valid until 1 January
Days left	246
MOT expiry date	8 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history


Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-06-06
Last registration	2023-12-09
Complete history	See info



Registration #1	2013-06-06	20 mi
Registration #2	2016-04-19	25.855 mi
Registration #3	2017-07-04	34.534 mi
Registration #4	2017-07-04	34.535 mi
Registration #5	2018-07-03	40.775 mi
Registration #6	2018-07-04	40.775 mi
Registration #7	2019-07-06	47.429 mi
Registration #8	2019-07-06	47.429 mi
Registration #9	2019-07-06	47.429 mi
Registration #10	2019-07-06	47.429 mi
Registration #11	2019-07-06	47.429 mi
Registration #12	2019-07-06	47.429 mi
Registration #13	2019-07-06	47.429 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1105 kg
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	A638J527