



report date: 2024-03-29

General information

Make	VAUXHALL
Model	AGILA S AC
Colour	Blue
Year of manufacture	2014
Top speed	109 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	118 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-10-10
Pictures	13
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-01
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	17
Total items failed	6

MOT #12	2023-10-26 08:01
MOT test number	754928261141
Result	✓ Passed
Next expiry date	2024-11-01
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11	2022-10-24 11:11
MOT test number	382081481876
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (0114) (5.2.3 (d) (ii))
Advice	N/s/f tyre has 3 cuts on outer side wall
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (0114) (5.2.3 (d) (ii))
Advice	Front exhaust heat shield loose

**MOT #10**

2022-10-24 08:55

MOT test number

284095803227

Result

✗ Failed

Advice N/s/f tyre has 3 cuts on outer side wall**Fail** Offside Windscreen wiper does not clear the windscreen effectively blade split (3.4 (b) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (0114) (5.2.3 (d) (ii))**Advice** Front exhaust heat shield loose**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (0114) (5.2.3 (d) (ii))**MOT #9**

2021-11-02 12:31

MOT test number

478520520854

Result

✓ Passed

Advice Front Tyre slightly damaged/cracking or perishing Both sides cracked and perishing (5.2.3 (d) (ii))**MOT #8**

2021-11-01 16:15

MOT test number

885118655258

Result

✗ Failed

Fail Offside Front Upper Shock absorbers has an excessively worn bush Top mount excessive play (5.3.2 (c))**Advice** Front Tyre slightly damaged/cracking or perishing Both sides cracked and perishing (5.2.3 (d) (ii))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #7**

2020-12-10 16:51

MOT test number

262728548941

Result

✓ Passed

Advice Offside Rear Nail in tyre marked in yellow**Advice** Both sides rear tyres wearing unevenly

**MOT #6** 2020-12-10 11:34**MOT test number** 359270155195**Result** ✗ Failed**Advice** Both sides rear tyres wearing unevenly**Advice** Offside Rear Nail in tyre marked in yellow**Fail** Offside Front Upper Macpherson strut mounting damaged and seriously weakened (5.3.3 (b) (i))**MOT #5** 2019-12-18 16:28**MOT test number** 237917084487**Result** ✓ Passed**MOT #4** 2018-12-07 14:45**MOT test number** 147349357416**Result** ✓ Passed**MOT #3** 2018-01-24 12:17**MOT test number** 739608864986**Result** ✓ Passed**MOT #2** 2017-01-26 16:40**MOT test number** 298789011902**Result** ✓ Passed**MOT #1** 2017-01-26 16:40**MOT test number** 590250575734**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too far to the right (1.8)**Pass with rectification** Nearside Front Headlamp aim too far to the right (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
1 November 2024

Tax status	Valid until 1 January
Days left	246
MOT expiry date	1 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 KY63EKZ
Plate since	2019-03-29
Current registration	 KY63EKZ
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-02-12
Last registration	2023-10-26
Complete history	See info



Registration #1	2014-02-12	10 mi
Registration #2	2017-01-26	26.162 mi
Registration #3	2017-01-26	26.162 mi
Registration #4	2018-01-24	32.060 mi
Registration #5	2018-12-07	36.957 mi
Registration #6	2019-12-18	43.088 mi
Registration #7	2020-12-10	46.006 mi
Registration #8	2021-05-20	50.000 mi
Registration #9	2021-05-20	50.000 mi
Registration #10	2021-05-20	50.000 mi
Registration #11	2021-05-20	50.000 mi
Registration #12	2021-05-20	50.000 mi
Registration #13	2021-05-20	50.000 mi
Registration #14	2021-05-20	50.000 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	1000 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	K12B - 1808086LUY