





General information

Make	MINI
Model	MINI FIRST
Colour	Silver
Year of manufacture	2010
Top speed	109 mph
0 - 60 mph	13.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	140 Nm at 2.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	127 g/km
CO2 label	D







Internet history

Entry 2	
Date	2023-02-07
Pictures	15
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-02-02
Pictures	0
Listing price	<u>View report</u>

source: autoonline.co.uk



MOT history

MOT expiry date	2024-03-07
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	15
Total items failed	2

MOT #13		2023-03-08 16:05
MOT test number		763587035729
Result		✓ Passed
Next expiry date		2024-03-07
Advice Front Brake disc worn,	pitted or scored, but not seriously weakened Bo	oth side (1.1.14 (a) (ii))
Advice Under vehicle corrode	d	
Advice Rear Brake disc worn,	pitted or scored, but not seriously weakened Bo	th side (1.1.14 (a) (ii))

MOT #12	2023-03-06 14:51
MOT test number	568182510420
Result	🗙 Failed
Fail Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both	side (1.1.14 (a) (ii))
Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both s	side (1.1.14 (a) (ii))
Advice Under vehicle corroded	



NA60FBY report date: 2024-03-29

MOT #11		2022-01-17 09:34
MOT test	number	865020245327
Result		✓ Passed
Advice	Nearside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #10	2021-02-05 16:33
MOT test number	705595562563
Result	✓ Passed

МОТ #9	2020-11-24 15:26
MOT test number	145262715012
Result	✓ Passed

MOT #8		2020-08-04 10:20
MOT test	number	275670440337
Result		✓ Passed
Advice	Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i	i))
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.1	L4 (a) (ii))
Advice	Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1	14 (a) (ii))

MOT #7		2019-08-08 11:36
MOT test	number	736566240317
Result		✓ Passed
Advice (a) (ii))	Offside Rear Inner Brake pad(s) wearing thin not clearly visible, further inspect	ion advised (1.1.13
Advice (1.1.13 (a)	Nearside Rear Inner Brake pad(s) wearing thin not clearly visible, further inspe (ii))	ction advised





MOT #6	2018-07-30 08:22
MOT test number	778935960217
Result	✓ Passed
MOT #5	2017-08-09 08:23
MOT test number	222529256548
Result	✓ Passed
MOT #4	2016-08-11 10:04
MOT test number	278762423304
Result	✓ Passed
MOT #3	2015-08-10 09:58
MOT test number	599122525293
Result	✓ Passed
MOT #2	2014-08-18 11:27
MOT test number	367550534486
Result	✓ Passed
MOT #1	2013-08-27 15:55
MOT test number	889449133298
Result	✓ Passed



Tax & MOT check

✓ Taxed	X MOT Expired:
1 March 2025	7 March 2024
Tax status	Valid until 1 March
Days left	306
MOT expiry date	7 March 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-





Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	e et al
Date	*
Category	AMP
Туре	

Extra MINI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Carrent registration	
Rate sizes	
Carrent registration	
Carrent registration Plate since	





Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow



RAGOFBY report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-09-29
Last registration	2023-03-08
Complete history	<u>See info</u>



Registration #1	2010-09-29	8 mi
Registration #2	2013-08-27	10.205 mi
Registration #3	2014-08-18	17.582 mi
Registration #4	2015-08-10	23.874 mi
Registration #5	2016-08-11	31.297 mi
Registration #6	2017-08-09	39.720 mi
Registration #7	2018-07-30	46.491 mi
Registration #8	2019-08-08	53.793 mi
Registration #9	8993-83-83	11.777 esi
-	8000.00.00 8000.00.00	11.227 est
Registration #9	8000.00.00 8000.00 8000.00	01.000 est 01.000 est 01.000 est
Registration #9 Registration #10	8000.00.00 8000.00.00 8000.00.00 8000.00.00	00.000 est 0.000 est 00.000 est 00.000 est
Registration #9 Registration #10 Registration #11	1000-20-20 1000-20-20 1000-20-20 1000-20-20 1000-20-20	01.000 est 01.000 est 01.000 est 01.000 est 01.000 est 01.000 est
Registration #9 Registration #10 Registration #11 Registration #12	1000.00.00 1000.00.00 1000.00.00 1000.00.00 1000.00.00 1000.00.00	00.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est
Registration #9Registration #10Registration #11Registration #12Registration #13	1000.00.00 1000.00.00 1000.00.00 1000.00.00 1000.00.00 1000.00.00 1000.00.00	00.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est

More info >





Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1060 kg
Max. allowed weight	1510 kg
Additional information	
Fuel tank capacity	40
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles	2
Engine number	A4061693