





report date: 2024-03-29

General information

Make	PEUGEOT
Model	107 ACTIVE
Colour	Red
Year of manufacture	2014
Top speed	99 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	А



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2021-07-08

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



SP14GFZ report date: 2024-03-29

MOT history

MOT expiry date	2024-06-29
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	14
Total items failed	5

MOT #11		2023-06-13 10:40
MOT test	number	695670326237
Result		✓ Passed
Next expi	ry date	2024-06-29
Advice (a) (i))	Front Lower Subframe mounting prescribed area is corroded but not consi	idered excessive (5.3.6
Advice	Rear exhaust corroded	
Advice	Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1	1.1.11 (c))
Advice	Nearside Front Suspension arm corroded but not seriously weakened (5.3	.3 (b) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #10	2022-06-15 15:14
MOT test number	183568444401
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #9 2022-06-15 10:48

MOT test number 105666541217

Result X Failed

Fail Offside Rear Brake pipe excessively corroded (1.1.11 (c))

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #8 2021-06-30 15:06

MOT test number 737895137893

Result
✓ Passed

MOT #7 2021-03-15 13:06

MOT test number 808230116777

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #6 2021-03-15 10:58

MOT test number 165302172515

Result X Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

MOT #5 2020-03-12 11:04

MOT test number 937687866983

Result ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #4		2019-03-09 09:48
MOT test	number	632641984388
Result		✓ Passed
MOT #3		2018-03-13 15:13
MOT test	number	328196037597
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit 2mm (4.1.E.1)	
Advice Nearside Front Tyre worn close to the legal limit 1.8mm (4.1.E.1)		
Advice	Nearside Rear tyre has cracks to tread but not deep enough to reach the ply of	or cord

MOT #2	2017-02-24 14:10
MOT test number	862396494825
Result	✓ Passed
MOT #1	2017-02-24 10:29
MOT test number	418714346710
Result	X Failed
Fail Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)	
Fail Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)	

CarCheck.co.uk page 5/12



SP14GFZ report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	29 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

More info >

Owner history	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

THEFT CONTRACTOR CONTR	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	UK ZIS
Plate since	
Current registration	UK ZIS
Plate since	

CarCheck.co.uk page 9/12



SP14GFZ report date: 2024-03-29

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-03-14
Last registration	2023-06-13
Complete history	See info



Registration #1	2014-03-14	26 mi
Registration #2	2017-02-24	13.559 mi
Registration #3	2017-02-24	13.562 mi
Registration #4	2018-03-13	20.492 mi
Registration #5	2019-03-09	29.422 mi
Registration #6	2020-03-12	38.270 mi
Registration #7	2021-03-15	40.802 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.177 mi
Registration #12		0.00 44
Registration #13		70.777 esc

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
S0567	
50569	

Safety ratings

NCAP rating	***
Adult	68%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	66%
Video	see crash video



Dimensions & weight

Width	1630 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	905 kg
Max. allowed weight	1190 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles 2

Engine number 7552662