



report date: 2024-03-29

General information

Make	VOLVO
Model	XC70 D SE AWD
Colour	Silver
Year of manufacture	2008
Top speed	118 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	163 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.9 mpg
Consumption extra urban	41.5 mpg
Consumption combined	34.0 mpg
CO2 emission	219 g/km
CO2 label	K





Internet history

Entry 3

Date 2023-01-30

Pictures 12

Listing price [View report](#)



source: cargurus.co.uk

Entry 2

Date 2022-09-10

Pictures 35

Listing price [View report](#)



source: cargurus.co.uk

Entry 1

Date 2022-06-15

Pictures 36

Listing price [View report](#)



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-23
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	10
Total items failed	2

MOT #15	2023-06-19 11:14
MOT test number	730446526063
Result	✓ Passed
Next expiry date	2024-06-23
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside front tyre inner edge slight wear

MOT #14	2022-06-24 16:00
MOT test number	525878947984
Result	✓ Passed

MOT #13	2021-05-05 14:21
MOT test number	819591809194
Result	✓ Passed
Advice	Nearside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Play in steering rack inner joint(s)
Advice	Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #12** 2020-05-21 09:52**MOT test number** 300685051989**Result** ✓ Passed**Advice** Nearside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Drag link end ball joint has slight play (2.1.3 (b) (i))**Advice** Offside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Drag link end ball joint has slight play (2.1.3 (b) (i))**MOT #11** 2019-05-21 09:43**MOT test number** 574534702537**Result** ✓ Passed**MOT #10** 2018-05-08 16:03**MOT test number** 470099765580**Result** ✓ Passed**MOT #9** 2018-05-08 16:03**MOT test number** 402963599740**Result** ✗ Failed**Pass with rectification** Front Front position lamp(s) not working (1.1.A.3b)**MOT #8** 2017-05-18 10:23**MOT test number** 215679188764**Result** ✓ Passed**MOT #7** 2016-05-24 13:45**MOT test number** 464359122127**Result** ✓ Passed



MOT #6	2015-05-22 10:24
---------------	------------------

MOT test number	638472845142
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2014-05-21 12:05
---------------	------------------

MOT test number	148891844197
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2014-05-21 12:05
---------------	------------------

MOT test number	416061144135
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Headlamp aim too low (1.8)
--------------------------------	----------------------------

MOT #3	2013-05-24 12:02
---------------	------------------

MOT test number	425874143141
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2012-05-10 11:58
---------------	------------------

MOT test number	527321732103
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2011-05-03 11:32
---------------	------------------

MOT test number	168573321149
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
23 June 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	23 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	AA08NEF
Plate since	2024-03-29
Current registration	AA08NEF
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-05-28
Last registration	2023-06-19
Complete history	See info



Registration #1	2008-05-28	7 mi
Registration #2	2011-05-03	34.274 mi
Registration #3	2012-05-10	43.122 mi
Registration #4	2013-05-24	50.578 mi
Registration #5	2014-05-21	56.892 mi
Registration #6	2015-05-22	63.475 mi
Registration #7	2016-05-24	67.311 mi
Registration #8	2017-05-18	73.585 mi
Registration #9	2018-05-08	78.421 mi
Registration #10	2019-05-20	81.277 mi
Registration #11	2020-05-20	85.277 mi
Registration #12	2021-05-20	89.277 mi
Registration #13	2022-05-20	93.277 mi
Registration #14	2023-05-20	97.277 mi
Registration #15	2024-05-20	101.277 mi
Registration #16	2025-05-20	105.277 mi
Registration #17	2026-05-20	109.277 mi
Registration #18	2027-05-20	113.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	


View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2142 mm
Height	1713 mm
Length	4628 mm
Wheel base	2774 mm
Kerb weight	1862 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	660312