





report date: 2024-03-29

General information

Make	VAUXHALL
Model	AGILA S ECOFLEX
Colour	Blue
Year of manufacture	2010
Top speed	99 mph
0 - 60 mph	14.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	64 BHP
Engine capacity	996 сс
Cylinders	3
Fuel type	Petrol
Consumption city	45.6 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/12



DS59OLU

report date: 2024-03-29

Internet history

Entry 2

Date 2021-05-23

Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-07-17
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	19
Total items failed	1

MOT #13	20	023-07-18 11:25
MOT test	number	533557324041
Result		✓ Passed
Next expi	ry date	2024-07-17
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	

MOT #12	2022-06-17 12:41
MOT test number	530244862389
Result	✓ Passed
Advice Nearside Rear brake pipe corroded but not excessive	

MOT #11	2021-05-10 15:19
MOT test number	211950276454
Result	✓ Passed

CarCheck.co.uk page 3/12



MAJOR

MAJOR

DS590LU

report date: 2024-03-29

MOT test number

Result

MAJOR Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MAJOR Nearside Front Service brake excessively fluctuating (1.2.1 (e))

MAJOR Front Windscreen washer provides insufficient washer liquid (3.5 (a))

Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Offside Front Service brake excessively binding (1.2.1 (f))

MOT #9

MOT test number

Result

Advice Little reserve travel on handbrake

MOT test number

Result

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Minor Offside Windscreen wiper blade defective (3.4 (b) (i))

MOT test number
610490619736

Result

Pass with rectification
Offside Headlamp aim too high (4.1.2 (a))

Advice
Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Minor
Offside Windscreen wiper blade defective (3.4 (b) (i))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #6		2018-01-11 11:35
MOT test	number	700628833832
Result		✓ Passed
MOT #5		2017-01-10 15:59
MOT test	number	396080787743
Result		✓ Passed
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Parking brake lever has little reserve travel (3.1.6b)	

MOT #4		2016-01-11 09:41
MOT test	number	611952667816
Result		✓ Passed
Advice	Brake pipe slightly corroded Both rear (3.6.B.2c)	
Advice	Nearside Rear Slight cracking	
Advice	Brake pipe slightly corroded Both front to rear (3.6.B.2c)	
Advice	Nearside Front Slight cracking	

MOT #3	2015-01-05 14:02
MOT test number	267125805040
Result	✓ Passed
MOT #2	2014-02-07 14:40
MOT test number	468678134034
Result	✓ Passed
MOT #1	2013-03-02 08:32
MOT test number	319391663050
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	17 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	

Date Date	
Category	



Extra VAUXHALL salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



DS590LU report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



DS59OLU

report date: 2024-03-29

More info >

Owner history

e met mistery	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlondere.	

THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	NK SIZ
Flate since	
Current registration	NK SIZ
Plate since	

CarCheck.co.uk page 9/12



DS59OLU

report date: 2024-03-29

Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-02-11
Last registration	2023-07-18
Complete history	See info



Registration #1	2010-02-11	9 mi
Registration #2	2013-03-02	23.080 mi
Registration #3	2014-02-07	29.737 mi
Registration #4	2015-01-05	32.921 mi
Registration #5	2016-01-11	39.861 mi
Registration #6	2017-01-10	47.110 mi
Registration #7	2018-01-11	50.513 mi
Registration #8	2019-01-15	54.816 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		0.00 44
Registration #15		11.777 ms

More info >

CarCheck.co.uk page 11/12



DS590LU report date: 2024-03-29

Safety ratings

NCAP rating	***
-------------	-----

Video <u>see crash video</u>



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	975 kg
Max. allowed weight	1485 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	1089195

CarCheck.co.uk page 12/12