



report date: 2024-03-29

General information

Make	FORD
Model	FUSION STYLE CLIMATE
Colour	Purple
Year of manufacture	2008
Top speed	102 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-11
Pictures	2
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-28
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	19
Total items failed	9

MOT #19	2024-01-25 17:20
MOT test number	842999804595
Result	✓ Passed
Next expiry date	2025-01-28
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #18	2024-01-25 14:32
MOT test number	637431159784
Result	✗ Failed
Fail	Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Offside Front Outer Tyre has a bulge, caused by separation or partial failure of its structure sidewall (5.2.3 (d) (ii))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #17** 2023-01-19 09:41**MOT test number** 685843565143**Result** ✓ Passed**Advice** Nearside rear tyre worn close to legal limit**Advice** Nearside front tyre worn on edge of tread**MOT #16** 2022-01-29 11:05**MOT test number** 690415232677**Result** ✓ Passed**Advice** Brake pipe corroded, covered in grease or other material Front to rear pipes covered in grease.
(1.1.11 (c))**MOT #15** 2022-01-27 13:47**MOT test number** 627272905295**Result** ✗ Failed**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Rear Valve stem seriously damaged (5.2.3 (j))**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Brake pipe corroded, covered in grease or other material Front to rear pipes covered in grease.
(1.1.11 (c))**MOT #14** 2021-03-01 10:10**MOT test number** 307554655985**Result** ✓ Passed**Advice** Offside wiper blade is beginning to split**MOT #13** 2020-03-02 10:07**MOT test number** 115689989071**Result** ✓ Passed

**MOT #12** 2019-02-25 15:42**MOT test number** 151635547162**Result** ✓ Passed**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #11** 2019-02-25 09:52**MOT test number** 839651877123**Result** ✗ Failed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**MOT #10** 2018-03-06 11:55**MOT test number** 802850572784**Result** ✓ Passed**MOT #9** 2017-03-06 09:55**MOT test number** 954320800876**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #8	2016-03-07 09:26
---------------	------------------

MOT test number	402651758871
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2015-03-02 14:17
---------------	------------------

MOT test number	886331265091
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2014-03-20 09:00
---------------	------------------

MOT test number	736189574020
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2013-02-27 10:57
---------------	------------------

MOT test number	647708453059
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2013-02-27 10:57
---------------	------------------

MOT test number	368948453077
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Nearside Stop lamp not working (1.2.1b)
--------------------------------	---

MOT #3	2012-03-20 12:59
---------------	------------------

MOT test number	347630782048
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2011-03-25 14:50
---------------	------------------

MOT test number	488834081088
------------------------	--------------

Result	✓ Passed
---------------	----------



MOT #1	2010-12-17 14:31
MOT test number	683031150386
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
28 January 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	28 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXX
Plate since	2023-03-29
Current registration	XXXXX
Plate since	2023-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-02-01
Last registration	2024-01-25
Complete history	See info



Registration #1	2008-02-01	29 mi
Registration #2	2010-12-17	12.563 mi
Registration #3	2011-03-25	13.039 mi
Registration #4	2012-03-20	22.764 mi
Registration #5	2013-02-27	28.445 mi
Registration #6	2014-03-20	32.469 mi
Registration #7	2015-03-02	41.086 mi
Registration #8	2016-03-07	49.232 mi
Registration #9	2017-03-06	57.744 mi
Registration #10	2018-03-06	64.476 mi
Registration #11	2019-03-06	71.208 mi
Registration #12	2020-03-06	77.940 mi
Registration #13	2021-03-06	84.672 mi
Registration #14	2022-03-06	91.404 mi
Registration #15	2023-03-06	98.136 mi
Registration #16	2024-01-25	104.868 mi
Registration #17	2024-01-25	104.868 mi
Registration #18	2024-01-25	104.868 mi
Registration #19	2024-01-25	104.868 mi
Registration #20	2024-01-25	104.868 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1199 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	8A48618