



report date: 2024-03-29

## General information

Make	VOLVO
Model	C70 D4 SE LUX
Colour	Black
Year of manufacture	2012
Top speed	134 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	175 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history

Entry 2

Date	2022-02-06
Pictures	33
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

Entry 1

Date	2021-11-20
Pictures	3
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2023-10-17
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	14
Total items failed	0

MOT #12	2022-10-06 12:50
MOT test number	343290121238
Result	✓ Passed
Next expiry date	2023-10-17
Advice	Covers fitted obstructing view
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

MOT #11	2022-10-05 08:34
MOT test number	601739635961
Result	✗ Failed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
MAJOR	Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt insecure (2.1.3 (g) (ii))
MAJOR	Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Covers fitted obstructing view
MAJOR	Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt insecure (2.1.3 (g) (ii))
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))



<b>MOT #10</b>	2021-10-01 13:40
----------------	------------------

<b>MOT test number</b>	432018275415
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #9</b>	2020-10-03 11:09
---------------	------------------

<b>MOT test number</b>	214125787236
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Rear registration plate deteriorating.
---------------	--

<b>MOT #8</b>	2019-10-09 14:12
---------------	------------------

<b>MOT test number</b>	364154904385
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #7</b>	2018-09-26 09:29
---------------	------------------

<b>MOT test number</b>	842137004946
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #6</b>	2018-09-25 11:59
---------------	------------------

<b>MOT test number</b>	375415428342
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>DANGEROUS</b>	Nearside Rear Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))
------------------	--

<b>Advice</b>	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
---------------	--

<b>MOT #5</b>	2017-10-18 14:50
---------------	------------------

<b>MOT test number</b>	693445046957
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2017-10-14 14:19
---------------	------------------

<b>MOT test number</b>	703873561039
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



MOT #3	2017-04-20 12:50
MOT test number	529741201823
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #2	2016-04-19 08:44
MOT test number	495646054142
Result	✓ Passed

MOT #1	2015-04-20 15:40
MOT test number	547120515110
Result	✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-04-27
Last registration	2022-10-06
Complete history	<a href="#">See info</a>



Registration #1	2012-04-27	6 mi
Registration #2	2015-04-20	29.817 mi
Registration #3	2016-04-19	38.015 mi
Registration #4	2017-04-20	44.058 mi
Registration #5	2017-10-14	47.271 mi
Registration #6	2017-10-18	47.271 mi
Registration #7	2018-09-25	54.912 mi
Registration #8	2018-09-26	54.912 mi
Registration #9	2019-05-20	55.377 mi
Registration #10	2019-05-20	55.377 mi
Registration #11	2019-05-20	55.377 mi
Registration #12	2019-05-20	55.377 mi
Registration #13	2019-05-20	55.377 mi
Registration #14	2019-05-20	55.377 mi
Registration #15	2019-05-20	55.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2025 mm
Height	1400 mm
Length	4615 mm
Wheel base	2640 mm
Kerb weight	1789 kg
Max. allowed weight	2150 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Engine number	1109685
---------------	---------