





General information

Make	ΤΟΥΟΤΑ
Model	PRIUS VVT-I T3
Colour	White
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	10.4 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	134 BHP
Max. torque	142 Nm at 4.000 rpm
Cylinders	4
Fuel type	Hybrid / Electric / (clean)
Consumption city	72.4 mpg
Consumption extra urban	76.4 mpg
Consumption combined	72.4 mpg





Internet history

E	n	tr	Ъ	1

Date Pictures 2021-10-11

Listing price

View report

4



source: cargurus.co.uk



MOT history	
MOT #10	2022-11-07 16:31
MOT test number	610722522986
Result	✓ Passed
Next expiry date	2023-11-25

МОТ #9	2021-11-26 14:55
MOT test number	657623855539
Result	✓ Passed

MOT #8	2021-03-27 12:4	1
MOT test	number 74689742178	9
Result	✓ Passe	d
Advice	Rear parking brake effort only just met = 16% - limit 15%	
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	• Offside Front Tyre worn close to legal limit/worn on edge bald on inner edge (5.2.3 (e))	
Advice (a) (i))	Front Brake disc worn, but not excessively both offside & nearside - slightly worn/lipped (1.1.14	
Advice (a) (ii))	Rear Brake disc worn, pitted or scored, but not seriously weakened both offside & nearside (1.1.14	

MOT #7	2020-09-03 07:38
MOT test number	977293515387
Result	✓ Passed
MOT #6	2020-02-28 09:45
MOT test number	829291704903
Result	✓ Passed
MOT #5	2019-09-03 07:33
MOT test number	474532822065
Result	✓ Passed





МОТ #4	2019-08-19 12:42	
MOT test number	561607412482	
Result	✓ Passed	
Advice Rear Tyre worn close to legal limit/worn on edge both side (5.2.3 (e))		
MOT #3	2019-08-19 12:42	
MOT test number	886232187731	
Result	🗙 Failed	
Pass with rectification Tyre pressure monitoring system malfunctioning or obviou (h))	usly inoperative (5.2.3	
Advice Rear Tyre worn close to legal limit/worn on edge both side (5.2.3 (e))		

MOT #2	2018-07-19 15:19
MOT test number	873842044851
Result	✓ Passed

MOT #1	2018-07-19 15:19
MOT test number	922815427576
Result	× Failed
Pass with rectification (b) (ii))	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4
Pass with rectification (b) (ii))	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	E	
Category		ARMPE
Туре		
Damage 2		AMPL
Damage 2	k	
Date		14
Category		AMP
Туре		

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-08-13
Last registration	2022-11-07
Complete history	See info



Registration #1	2015-08-13	8 mi
Registration #2	2018-07-19	42.366 mi
Registration #3	2018-07-19	42.366 mi
Registration #4	2019-08-19	48.603 mi
Registration #5	2019-08-19	48.603 mi
Registration #6	2019-09-03	48.867 mi
Registration #7		11.777 mi
Registration #8		11.117 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 est





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	88%
Children	82%
Pedestrian	68%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight	
Width	1725 mm
Height	1490 mm
Length	4450 mm
Wheel base	2700 mm
Kerb weight	1425 kg
Max. allowed weight	1805 kg
Additional information	
Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 10/10