





report date: 2024-03-29

## General information

Make	VOLKSWAGEN	
Model	AMAROK DC TDI HIGHLINE 4MOTION	
Colour	Blue	
Year of manufacture	2015	
Top speed	108 mph	
Gearbox	8 speed automatic	

# Engine & fuel consumption

Power	180 BHP
Max. torque	420 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	38.2 mpg
Consumption combined	35.3 mpg
CO2 emission	211 g/km
CO2 label	K



CarCheck.co.uk page 1/13



report date: 2024-03-29

# Internet history

## Entry 1

Date 2021-07-21

Pictures 26

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-02-08
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	25
Total items failed	9

MOT #9	2023-02-09 14:06	
MOT test number	128045729268	
Result	✓ Passed	
Next expiry date	2024-02-08	
Advice Oil leak, but not excessive Intercooler area (8.4.1 (a) (i))		
Advice Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement D Bush (5.3.4 (a) (i))		
Advice Nearside Rear Tail lamp damaged but not effecting light output		
Minor Windscreen damaged but not adversely affecting driver's view Stone Chip (3.2 (a) (i))		
Advice Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement D Bush (5.3.4 (a) (i))		

CarCheck.co.uk page 3/13



report date: 2024-03-29

**MOT #8** 2023-02-09 12:02 **MOT** test number 134191058222 Result **X** Failed Fail Parking brake efficiency below requirements (1.4.2 (a) (i)) **Advice** Nearside Rear Tail lamp damaged but not effecting light output **Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement D Bush (5.3.4 (a) (i)) Minor Windscreen damaged but not adversely affecting driver's view Stone Chip (3.2 (a) (i)) Advice Offside Front Service brake binding but not excessively (1.2.1 (f)) **Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement D Bush (5.3.4 (a) (i)) **Advice** Oil leak, but not excessive Intercooler area (8.4.1 (a) (i))

MOT #7

MOT test number

Result

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT test number

532589383763

Result

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice

Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail

Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice

Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT test number

Result

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #4** 2021-05-17 10:50 **MOT** test number 674601373834 Result **X** Failed **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Fail Central Stop lamp(s) not working high level (4.3.1 (a) (ii)) Fail Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b)) Nearside Headlamp aim too low (4.1.2 (a)) Fail Fail Reversing lamp inoperative (4.6.1 (a)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Fail Nearside Rear Position lamp showing white light to the rear (4.2.3 (a) (ii)) Fail Offside Rear Service brake excessively binding (1.2.1 (f)) Parking brake efficiency below requirements (1.4.2 (a) (i)) Fail

MOT #3		2020-06-03 10:21
MOT test	number	298609078524
Result		✓ Passed
Advice	Offside Front Shock absorbers light misting of oil or has limited damping eff	ect (5.3.2 (b))
Advice	Offside Rear brake slightly binding	

CarCheck.co.uk page 5/13



MOT test number

Result

Advice Hand brake efficiency just met

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Crack in windscreen not effecting drivers view

MOT #1

MOT test number

Result

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

CarCheck.co.uk page 6/13



## Tax & MOT check

Tax expired: 11 May 2023



X MOT

Expired: 8 February 2024

Tax status	Expired at 11 May 2023
Days left	355 days too late
MOT expiry date	8 February 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 7/13




report date: 2024-03-29

## Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra VOLKSWAGEN salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



## Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	
*********	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NIN
Plate since	
Current registration	NK NE
Plate since	
	More info >

CarCheck.co.uk page 10/13



## Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-06-30
Last registration	2023-02-09
Complete history	See info



Registration #1	2015-06-30	14 mi
Registration #2	2018-06-04	77.924 mi
Registration #3	2019-06-20	101.083 mi
Registration #4	2020-06-03	116.648 mi
Registration #5	2021-05-17	128.547 mi
Registration #6	2021-05-20	128.615 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		0.777 46

More info >

CarCheck.co.uk page 12/13



## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	86%
Children	64%
Pedestrian	47%
Safety systems	57%
Overall rating	71%
Video	see crash video



# Dimensions & weight

Width	2228 mm
Height	1834 mm
Length	5254 mm
Wheel base	3000 mm
Kerb weight	2093 kg
Max. allowed weight	3170 kg

## Additional information

Fuel delivery	Direct Injection
Number of seats	5
Number of axles	2
CarChack co.uk	nago 12/12

CarCheck.co.uk page 13/13

**Engine number** 

CSHA108850