



report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA EXCLUSIV CDTI S/S
Colour	Silver
Year of manufacture	2013
Top speed	117 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg
CO2 emission	160 g/km
CO2 label	G







Internet history

Entry 2


Date	2021-11-04
Pictures	26
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

Entry 1

Date	2021-07-07
Pictures	26
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)



## MOT history

MOT expiry date	2025-01-10
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	20
Total items failed	9

## MOT #14 2023-12-15 11:28

MOT test number 741670525979

Result ✓ Passed

Next expiry date 2025-01-10

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both fronts n/s and o/s (1.1.14 (a) (ii))

**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

**Advice** Front Brake pad(s) wearing thin both front n/s and o/s (1.1.13 (a) (ii))

## MOT #13 2023-01-11 09:11

MOT test number 812089517320

Result ✓ Passed

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

## MOT #12 2021-12-02 12:12

MOT test number 952707702593

Result ✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11** 2021-12-02 12:12**MOT test number** 544465205869**Result** ✗ Failed**Pass with rectification** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2021-03-24 09:07**MOT test number** 657255978965**Result** ✓ Passed**MOT #9** 2021-03-22 15:06**MOT test number** 357164792017**Result** ✗ Failed**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Offside Rear Brake pipe excessively corroded to front (1.1.11 (c))**Fail** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #8** 2020-03-17 10:26**MOT test number** 465063055307**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

**MOT #7** 2019-03-20 15:12**MOT test number** 980387133837**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #6** 2019-03-19 12:44**MOT test number** 937961272882**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm worn to 1mm on inner (5.2.3 (e))**MOT #5** 2018-03-26 10:21**MOT test number** 713934726802**Result** ✓ Passed**MOT #4** 2018-03-26 10:21**MOT test number** 906486504372**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Stop lamp not working (1.2.1b)**MOT #3** 2017-03-15 15:02**MOT test number** 624457309417**Result** ✓ Passed



MOT #2	2017-03-15 11:43
MOT test number	423984121831
Result	✗ Failed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Fail	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Offside Front Nail in tyre

MOT #1	2016-03-29 13:55
MOT test number	451459152774
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
10 January 2025

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	62
<b>MOT expiry date</b>	10 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	MA13VSX
Plate since	2019-06-29
Current registration	MA13VSX
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2013-03-31
Last registration	2023-12-15
Complete history	<a href="#">See info</a>



Registration #1	2013-03-31	9 mi
Registration #2	2016-03-29	40.057 mi
Registration #3	2017-03-15	51.499 mi
Registration #4	2017-03-15	51.499 mi
Registration #5	2018-03-26	61.122 mi
Registration #6	2018-03-26	61.122 mi
Registration #7	2019-03-19	70.585 mi
Registration #8	2019-03-20	70.585 mi
Registration #9	2020-03-17	79.545 mi
Registration #10	2020-03-20	80.277 mi
Registration #11	2020-03-20	80.277 mi
Registration #12	2020-03-20	80.277 mi
Registration #13	2020-03-20	80.277 mi
Registration #14	2020-03-20	80.277 mi
Registration #15	2020-03-20	80.277 mi
Registration #16	2020-03-20	80.277 mi
Registration #17	2020-03-20	80.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2085 mm
Height	1761 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1836 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 263998K LNQ