



report date: 2024-03-28

General information

Make	NISSAN
Model	PIXO N-TEC
Colour	Red
Year of manufacture	-
Top speed	96 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-05
Pictures	24
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #16	2023-07-12 11:32
MOT test number	646842021564
Result	✓ Passed
Next expiry date	2024-07-13
Minor	Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Offside Rear lamp casing cracked
Advice	Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))
Minor	Offside Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #15	2022-06-30 09:26
MOT test number	236709803437
Result	✓ Passed
Minor	Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated slight weep (6.1.7 (g) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing 155/65/14 (5.2.3 (d) (ii))
Minor	Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated slight weep (6.1.7 (g) (i))

MOT #14	2022-06-29 10:14
MOT test number	549700107016
Result	✗ Failed
Minor	Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated slight weep (6.1.7 (g) (i))
Fail	Horn not working (7.7 (a))
Minor	Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated slight weep (6.1.7 (g) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing 155/65/14 (5.2.3 (d) (ii))

MOT #13	2021-07-14 16:27
MOT test number	488833460590
Result	✓ Passed

**MOT #12** 2020-09-30 15:30**MOT test number** 899935339798**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge tyre on 3mm & wearing on outer edge 155/65/15 (5.2.3 (e))**MOT #11** 2019-10-14 10:51**MOT test number** 151499140589**Result** ✓ Passed**Advice** Headlamp has a product on the lens but not seriously reducing light output Both sides (4.1.4 (b))**MOT #10** 2018-10-11 12:03**MOT test number** 724642414538**Result** ✓ Passed**MOT #9** 2018-10-11 09:51**MOT test number** 125926156830**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #8** 2017-10-23 12:46**MOT test number** 565105891273**Result** ✓ Passed**MOT #7** 2016-11-03 12:06**MOT test number** 725366666610**Result** ✓ Passed

**MOT #6** 2015-11-11 13:05**MOT test number** 356419997090**Result** ✓ Passed

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 23% (3.7.B.5b)

Advice Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 21% (3.7.B.5b)

MOT #5 2014-12-04 12:01**MOT test number** 887668534362**Result** ✓ Passed

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

Advice Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

MOT #4 2014-12-04 12:01**MOT test number** 307748634303**Result** ✗ Failed

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

MOT #3 2014-01-09 12:49**MOT test number** 156129704029**Result** ✓ Passed**MOT #2** 2013-01-21 09:59**MOT test number** 255841823008**Result** ✓ Passed

Notice Both front tyres are scuffed out on the edge's



MOT #1	2013-01-21 09:59
MOT test number	546021723008
Result	✗ Failed
<div><div>Notice</div>Both front tyres are scuffed out on the edge's</div> <div><div>Pass with rectification</div>Nearside Headlamp aim too low (1.8)</div>	



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-20
Current registration	*****
Plate since	2019-06-20

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-02-22
Last registration	2023-07-12
Complete history	See info



Registration #1	2010-02-22	16 mi
Registration #2	2013-01-21	13.429 mi
Registration #3	2014-01-09	18.549 mi
Registration #4	2014-12-04	23.988 mi
Registration #5	2015-11-11	28.004 mi
Registration #6	2016-11-03	32.448 mi
Registration #7	2017-10-23	36.825 mi
Registration #8	2018-10-11	39.981 mi
Registration #9	2019-05-29	45.277 mi
Registration #10	2019-05-29	50.573 mi
Registration #11	2019-05-29	55.869 mi
Registration #12	2019-05-29	61.165 mi
Registration #13	2019-05-29	66.461 mi
Registration #14	2019-05-29	71.757 mi
Registration #15	2019-05-29	77.053 mi
Registration #16	2019-05-29	82.349 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	112085