



report date: 2024-03-29

General information

Make	CITROEN
Model	C2 HDI VTR
Colour	Black
Year of manufacture	2009
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	160 Nm at 2.000 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	76.4 mpg
Consumption combined	65.7 mpg
CO2 emission	113 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-09-29
Pictures	15
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-09-27
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	20
Total items failed	11

MOT #17	2023-09-27 15:20
MOT test number	682361314796
Result	✓ Passed
Next expiry date	2024-09-27

MOT #16	2023-09-27 15:20
MOT test number	508273151943
Result	✗ Failed
Pass with rectification	Nearside Rear Position lamp not working (4.2.1 (a) (ii))

MOT #15	2022-09-27 11:49
MOT test number	392791230172
Result	✓ Passed
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #14	2021-09-28 15:08
MOT test number	639451275464
Result	✓ Passed
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #13**

2021-09-24 16:23

**MOT test number**

835767607887

**Result**

✗ Failed

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**MAJOR** Offside Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))**MOT #12**

2020-09-09 11:21

**MOT test number**

601533755207

**Result**

✓ Passed

**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11**

2019-04-12 09:04

**MOT test number**

322722672018

**Result**

✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10**

2018-04-06 13:58

**MOT test number**

461959345242

**Result**

✓ Passed

**MOT #9** 2018-04-06 10:18**MOT test number** 539262228805**Result** ✗ Failed

**Fail** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Fail** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**MOT #8** 2017-04-14 12:57**MOT test number** 900822170957**Result** ✓ Passed**MOT #7** 2017-03-17 10:40**MOT test number** 117832905336**Result** ✗ Failed

**Fail** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Fail** Suspension arm rubber bush bonding deteriorated resulting in excessive movement nearside front lower arm rearmost bush (2.4.G.2)

**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

**Fail** Suspension arm rubber bush bonding deteriorated resulting in excessive movement offside front lower arm rearmost bush (2.4.G.2)

**Fail** Steering column top bearing excessively worn (2.1.2c)

**MOT #6** 2016-03-18 13:53**MOT test number** 105686222246**Result** ✓ Passed

**MOT #5** 2016-03-12 11:42**MOT test number** 745231042419**Result** ✗ Failed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Exhaust has a major leak of exhaust gases Centre pipe. (7.1.2)**Advice** Rear wiper blade split.**MOT #4** 2015-03-23 17:11**MOT test number** 937472285090**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-03-22 11:27**MOT test number** 739471984037**Result** ✓ Passed**MOT #2** 2014-03-22 11:27**MOT test number** 547541784012**Result** ✗ Failed**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)



MOT #1	2013-03-23 12:52
MOT test number	497402983099
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
27 September 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	186
<b>MOT expiry date</b>	27 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-12-24
Last registration	2023-09-27
Complete history	<a href="#">See info</a>



Registration #1	2009-12-24	22 mi
Registration #2	2013-03-23	40.086 mi
Registration #3	2014-03-22	49.688 mi
Registration #4	2015-03-23	52.349 mi
Registration #5	2016-03-12	56.922 mi
Registration #6	2016-03-18	57.003 mi
Registration #7	2017-03-17	60.354 mi
Registration #8	2017-04-14	60.393 mi
Registration #9	2018-04-06	67.557 mi
Registration #10	2019-03-27	75.277 mi
Registration #11	2019-03-27	75.277 mi
Registration #12	2019-03-27	75.277 mi
Registration #13	2019-03-27	75.277 mi
Registration #14	2019-03-27	75.277 mi
Registration #15	2019-03-27	75.277 mi
Registration #16	2019-03-27	75.277 mi
Registration #17	2019-03-27	75.277 mi
Registration #18	2019-03-27	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1659 mm
Height	1477 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	1003 kg
Max. allowed weight	1391 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FDBE2550527